ALLEGAN COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE

12

Filing Requirement of Act 74, Mich. P.A. 1970 For comers in ALLEGAN Corner Code ## Located In: T-2N R -12W C-13 SE-31 1. Public Land Survey WATSON TWP _ R Π 7 R R ڝ 2. Property Controlling R in Section S R Miscellaneous S R Register of Deeds Stamp & File Number Property in Sec. S ____, Recorded Plat 5. Private Claims ___ FEBRUARY 9 BASIL ANDRESS . in a lield survey on . I PROTE ANDRESS, in a field survey on FROMENT 9, 1997.

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: G.L.O. DEC. 1830 LUCIUS LYON, DS WEST SOUTH SIDE SEC-32, T-2N, R-12W APPROVED REMONUMENTATION CORNER 80.00 ELM 18 FOR CORNER SECTIONS 31 & 32 P.A. 345 OF 1990 ALLEGAN COUNTY OLD NOTES/ COUNTY SURVEYOR'S OFFICE
WITNESS: MAPLE 12" SE 34 1/2 LKS. DATE APPROVED COUNTY REP.______ CONTINUED ON BACK OF CERTIFICATE B. Description of corner evidence found and/or method applied in restoring or reestablishing corner. FD. STONE W/ 1/2" IRON OVER IT PER L.C.R.C. . TRAVEY & THIS CORNER IS ACCEPTED AS A CAREFUL AND FAITHFUL PERPETUATION OF THE POSITION OF THE ORIGINAL CORNER. APPROVED BY THE ALLEGAN COUNTY REMONIMENTATION PEER GROUP 3-9-94. 150 COW WALLY C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: REPLACED THE 1/2" IRON AND STONE W/ STD. ALLEGAN CO. MON. (3/4" \times 36" BASIL J. BAS STEEL PIN & CAP) NAIL & REMON. WASHER S SDE 18" POPLAR N 80 W 147.40' EAST EDGE ST. SIGN POST N 65 W 63.03' NAIL & REMON. WASHER NW SDE 4" POPLAR N 30 E 80.31' NAIL & REMON. WASHER SW SDE 6" ELM S 35 E 22.43' BASIL J ANDRESS,JR. LAND SURVEYOR EAST EDGE EAST LEG OF DIRECTIONAL SIGN S 20 W 15.05' EAST EDGE STOP SIGN POST S 55 W 75.83' NO. 30075 ZAHD SURIE NAIL & REMON. WASHER NW COR RR TIE FE POST S 75 W 119.21'
C/L 112TH AVE (GRAVEL) NORTH 3' +/STD. ALLEGAN CO. MON. (NE COR SEC-6, OTSEGO TWP.) WEST 83.08'

Date 4-11-94-

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971

SHEET 1 OF 2

REVISED HAY 14, 1975 REVISED JAN., 1983

Signed by Sap

Surveyor's Michigan License No.

118FR 004 PAGE 372

300 7*5*

LIBER 004 PAGE 373

A. DESCRIPTION OF CRIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION.

9-18-72 DONALD A. RATEKIN, CS L.C.R.C. L-2,P-30

FD. STONE & SET 1/2" RE-ROD OVER
WITNESSES: 8" & 12" TWIN OAK N20E 101.92'
ST. SIGN N75W 79.25'
DIRECTIONAL SIGN, EAST LEG S25W 15.68'
NE COR SEC-6 OTSECO TWP. WEST 83.08'

DIST WEST TO 1/8 POST 1317.42'
CONT WEST TO 1/4 COR 1317.42'

SUNVEY S REMONUMENTATION

MOV I 1995.

COMMISSION