ALLEGAN COUNTY REMONUMENTATION

APR 2 5 1995

 ${\tt UBER}0005_{\tt PAGE}018$

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

MOISSHMM		Filing Requirement of Act 74, Mich. F.A. 1970		AILEGIS AILEGIS	
. Allegan	l County)	Located In: · · Corn	er Code ##		<u>:</u>
	~~,	Clyde Township	_	Charles 19	_
1. Public La	nd Survey	T 2 N R 15 W E-1	3		i]
		T R		23-5 (=)	J
		ŢR		9: 1	-
	Controlling	STR		- to 54	
 Property in Section 	-	STR			
3. Miscellan		ST	R	egister of Deeds Stamp & File Number	er
Property	in Sec.	\$ T B			
d Lot No	(Recorded Plat		- ABCDEFGHIJK	K L
5 Private C	laims	Neodica i Mi		_	Ť
•• • • • • • • • • • • • • • • • • • • •	-			2 - 5 5 3 2 -	十
	•			3 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	\top
	T Minaka	11 December 4	94	5	Τ'
do barabu cart	ity that under re	Lin a field survey on <u>December 4,</u> quirements of P.A. 74, Michigan P.A. of 1970, the	e corner points mentioned	6 , 17 , 6 , 15 , 14	Τ.
in lines 1 and	2 ahove were i	ic conformance with regulations and rules the	erelore as required in the	7 1 1 1 1	I '
current manua	I of survey instr	ructions of the United States Department of the a Court of Law and/or that the corner points me	e interior, bureau of Land entioned in lines 3, 4 and 5	8 19 20 21 22 23	\perp
shove were in	conformance w	ith the rules of the Michigan Board of Land Sur	veyors or by a Decree of a		Ľ
Court of Law	established.	re-established, monumented, re-monumente	ed, recovered, lound as	10 30 20 20 27 36	<u></u>
expressed bel		corners, all in the same town and range,	may be recorded		፲፟
	more than 4 (his certificate		may no recorded	12 31 32 33 34 35	4
				13	丄
A. Descript	ion of original	monument and accessories and/or subs	equent restoration:	CARD 1/2" IRON FD (1968)	
E-13		1831 SET POST AT 80 CHAINS	CENTER OF N-S R	D BAST 31.75'	
)AK 7 N72E 14 LKS 9 N45-1/2W 17 LKS	POWER POLE	NW 51.0'	
	PINE	9 N45-1/2W 17 LKS ENER EAST 125.40'	CENTER 18" CONC	BLOCK WSW 14.5'	
	MITCHEL	L 1984 FD 3/4" PIPE	2635,81' N. TO	E1/4 POST - 2636.60' 1994	
	POWER I	POLE NW 51.0'	SIGN POST NAW	45.1'	
	8" TW (OAK NE 67.3'			
	CENTER	OF N-S RD EAST 15.5'			
	•				
B. Descript	ion of corner	evidence found and/or method applied in	restoring or reestablishin	ng corner:	
E-13	FOUND :	3/4" PIPE FROM WITNESSES AND	ACCEPTED ITS LOCAT	TION AS A CAREFUL AND FAITH	IFUI
	PERPET	UATION OF THE POSITION OF THE	ORIGINAL CORNER.	222	
				ST COF MICH.	
				Sen Ch	Ł
		A BOD OVED REMON	UMENTATION CORNER	* GEONGET /*	ľ
		P.A. 34	45 OF 1990 AN COUNTY /	* PROFESSIONAL 1	* }
•		DATE APPROVED	11-29-94	S SUPPREYOR	. }
		COUNTY REP.	to de Contractor	19018 E	7
			•	B SF	F
				POFESSION	
			ad to nernetuste location	the position of the corner:	
	tion of monum	nent for corner and accessories establish REPLACED PIPE WITH 3/4" X 3	EU IO PEIDEIDAIS IOCSIIIS	AN CO BRMON CAP	
E-13		REPLACED PIPE WITH 3/4" X 3 mon tag & nail in West side o	o tik mili yrreda	AZ. 150° 78.70'	
	A.C. re	mon tag & nail in west side o mon tag & nail in South side	of 12" Maple	AZ. 265° 51.12'	
	A.C. re	mon tag & nail in SW side of	Power Pole	AZ. 320° 51.41'	
	A.C. re	mon tag & nail in SE side of	20" twin Oak	AZ. 35° 67.50°	
	Lee Tow	mship Corner E-1		AZ. 90° 125.47'	
	Center	of North-South asphalt road		AZ. 90° 15.6'	
		/			
•	\mathcal{U}_{\cdot}	ora J. Mitchell	- Deran	nber 12, 1994	
Signed by	Δle	orge V. 1 sciones	Date Decem		