

SURVEY  
REMONUMENTATION

APR 29 1999

SECTION

ALLEGAN COUNTY REMONUMENTATION  
LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

FILED

1/28/1999 2:44:39 PM

For corners in

Allegan  
(County)

Located In:

Corner Code #

1. Public Land Survey

T3N R15W

D-1

T R  
T R  
T R

North 1/4 corner,  
Section 5, Manlius  
Twp.

2. Property Controlling  
in Section

S T R  
S T R

3. Miscellaneous  
Property in Sec.

S T R  
S T R

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_

5. Private Claims \_\_\_\_\_

I, Steve Lampen, in a field survey on December 4, 1998, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

**NOTE:** Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

D-1  
GLO - not set by GLO

Hicks - 1874

D-1 to C-1 = 40.25 ch.

D-1 to E-1 = 40.25 ch.

Road Commission

12" Maple NE 65.81

Power pole SW 86.41

1" Maple 64.69

Bolt on Telephone pedestal SW 57.23

Fillmore corner lies 162.36 East 162.33

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

D-1 Found 1" iron in monument box 0.07' North of the South line of Section 32, Town 4 North, Range 15 West.

12" Maple NE 65.81 Power pole SW 86.49 Fillmore corner East 162.36

D-1 to C-1 = 2648.58 D-1 to E-1 = 2647.22

Replaced iron with 3/4"x24" Allegan County Remonumentation iron and cap on the South line of Section 32, Town 4 North, Range 15 West. This corner not monumented by the original GLO Survey. This position is Accepted as the best available evidence of the position of the corner.

Traversed 2638 ft. on road.

This corner was approved by the Allegan County Remonumentation Peer Group on December 8, 1998.

APPROVED REMONUMENTATION CORNER

P.A. 345 OF 1990

ALLEGAN COUNTY

DATE APPROVED DEC. 8, 1998

COUNTY REP. *Steve Lampen*

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

D-1 3/4"x24" Allegan County Remonumentation iron and cap in monument on the South line of Section 32, Town 4 North, Range 15 West.

Azimuth = Michigan State Plane grid direction

NW corner house foundation 23° 22' 116.46

SE corner garage foundation 52° 53' 155.37

Power pole remonumentation tag in S side 282° 52' 162.64

Power pole remonumentation tag in NW side 210° 29' 86.48

Centerline gravel road towards the South 90° 10.

D-13, Town 4N, Range 15 West 90° 25' 162.30



Signed by *Steven Lampen*

Date *JANUARY 11, 1999*

Surveyor's Michigan License No. 37279

LIBERO 006 PAGE 84