APR 0 7 1998

Allegan County Remonumentation

LAND CORNER RECORDATION CERTIFICATE

For corners ISECTIO	Filing Require	ement of Act 74, Mich. P.A. 1970	8
Allegan	Located In:	Corner Code ≠#	T MY TANK
(County)		33,113. 0033 344	FIL JAN 21
Public Land Survey	T <u>4N</u> R <u>12W</u> T R T R	J-1 (N ¹ / ₂ , 2) Dorr Twp.	ED 1 PN 1:21 2 Example States and PUSS.
Property Controlling in Section	S T R S T R		21
 Miscellaneous Property in Sec. 	S T R S T R	Re	egister of Deeds Stamp & File Number
4. Lot No , R	ecorded Plat		- ABCDEFGHIJKLI
5. Private Claims			
•			3 6 5 4 3 2 4 1 3
			4 , , , , , , , , , , , , , , , , , , ,
John C. Bueche	in a field survey onJu	1y 9 19 97	5
do hereby certify that under rec	juirements of P.A. 74, Michigan P.A.	of 1970, the corner points mentioned	6 10 17 15 15
		d rules therefore as required in the ment of the interior, Bureau of Land	7
		rpoints mentioned in lines 3, 4 and 5	
2		Land Surveyors or by a Decree of a	19-120-1-21-22-23-24-
	e-established, monumented, re-n	nonumented, recovered, found as	10 30 30 30 37 36 36
expressed below:			30 20 20 20 20
NOTE: Not more than 4 corners, all in the same town and range, may be recorded			"
on this certificate.			12 31 32 33 34 35 36
A. Description of original i	monument and accessories and	/or subsequent restoration:	13 ()
J-1 GLO - LC	RC L1, P92, Aug., 1971	LCRC L1, P186, April, 1972	LCRC L3, P93
	et 1½" iron well point ½ way		Aug., 1976
	etween NE & NW on old	Nail side 6" W. Cherry	Set rebar by prop.
	nce South	SW 30.28'	meas, on line 5¼ &
	Cherry S 30° W 29.9'	SE cor. hse, ENE 100,82'	SW 35, 5-12
	cor. hse. fnd. N 60° E 100.8		8" W. Cherry S 10° W 26.42'
	V cor, block garg, N 25° E 78		TP N 20° W 35.0'
	iron East 1.18'	•	4" Ash S 5° E 31.69'
· •	HOH Last 1.10		OVER
B. Description of corner e	vidence found and/or method a	pplied in restoring or reestablishing	
J-1 Found 11/	" well point	AA.	PROVED REMONUMENTATION CORNER
	wit. & wit. LCRC I-186	Set PK as per wit.	P.A. 345 OF 1990 ALLEGAN COUNTY
, in partitions			ATE APPROVED 7-8-97
		4 check OK	DUNTY REP. K.V.O.
Fnd. capped l	DAA rerod; not as per wit.		
We have 2 ex	isting irons, the wit. from LCF	RC 3, 93 & 3, 295 do not check ei	ther iron.
(See back for			
This position	not established by original g o	vernment surveyors. This monun	nent is accepted
as the best av	vailable evidence of the positi	on of the corner.	,
Peer group	approved July 8, 1997	'• ·	
C. Description of monume	nt for corner and accessories e	stablished to perpetuate locating t	he position of the corner:
		th cap) in bit. road on South line o	
	. alum. siding N 22° E 80.22'	ar supplies site roug on booth line	in to tribothe se are 140181
_ -	fnd, to hse, N 53° E 107.40'		Marine Sanda Sand
	n Co, Remon, Tag in N side 1	2"W Cherry S 60° E 40 34"	Of MICHIGAN
	n Co. Remon. Tag in W side i		# 57 \ 14 h
	n Co. Remon. Tag in VV side n Co. Remon. Tag in SE side		JOHN C. BUECHE A NAMB SURVEYOR
	apped rerod East 4.45'	14 7681 U U 1 11 UU.2U	* BUECHE **
14(-111-40)	Appearation mast 4.45		SURVEYOR . E

Well point 9.82' East & 0.60' South Kent Co. Mon. E 10.61' (S¼ 35, 5-12) On C/L bit. E-W Signed by John C. Bueche, P.S. Surveyor's Michigan License No. 13027

UEER 0006 PAGE 075

Sheet I of 2

LCRC L3, P295, Sept., 1980
Found rerod checks L3, P93
Spk. in 6" Ash S 5° E 31.66'
Nail in side TP N 20° W 34.99'
SW cor. garg. (alum. siding) NE 80.36'
½" iron East 10.61'
Spk. in side 8" Ash SW 38.18'

Exxel survey Nov., 1980 - iron E 10.61* MVK survey Jan., 1972 - same wit. as L1, P183

