

ALLEGAN COUNTY REMONUMENTATION
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Allegan
(County)

Located in:

Corner Code #

1. Public Land Survey T 4N R 13W G-7
T R Sec. 15, 16,
T R 21 & 22
T R Salem Twp.
2. Property Controlling S T R
in Section S T R
3. Miscellaneous S T R
Property in Sec. S T R

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat
5. Private Claims

I, Kirk VanOrder, in a field survey on December 14, 19 93
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the
current manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a
Court of Law; established, re-established, monumented, re-monumented, recovered, found as
expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- G-7
- GLO set post @ 80.00 chains North of G-9.
 - 18" Beech N70°W 10 links
 - 28" Beech N88°E 45 links
 - Stream 825' South, 33' wide
 - MacDougall notes, 10-2-1899, stone
 - 18" Ash S, SW 52.50'
 - Post SE 46'
 - 27" Locust SE 8"
 - Road Commission 1925 15.4' N. of C/L
 - 30" Ash S, SW 52.50'
 - 8" Locust W, NW 51.30'
 - 8" Locust NE 49.60'
 - LCRC (L.1, P.342) 4-11-1972
 - Fd. 1½" iron in mon. box
 - K.V.O. survey 11-20-1987 #87-1489
 - Fd. 1½" iron in mon. box
 - Support pole SW 68.02'
 - C/L well cap NW 86.65'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner.

- G-7
- Found 1½" x 11" iron rod in monument box. Have reason to believe it was
resting on top of stone.
- | | | |
|----------------------|----|--------|
| Support Pole | SW | 68.02' |
| C/L well cap | NW | 86.65' |
| C/L top conc. marker | NE | 55.58' |
| C/L Stop sign | SE | 59.5' |

Accepted as a careful and faithful perpetuation of the position of the
original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- G-7
- Replaced 1½" iron rod with standard Allegan Co. monument (¾" x 14" steel
rod with red plastic cap).
- | | | |
|---|--------------|---------|
| SW face of concrete project marker | AZ. 37°50'± | 55.36' |
| C/L gas valve box | AZ. 137°43'± | 61.00' |
| Nail & Allegan Co. Remon. tag in NW side of P. Pole | AZ. 213°42'± | 238.24' |
| Nail & Allegan Co. Remon. tag in N side of P. Pole | AZ. 259°06'± | 150.98' |
| C/L 6" diameter well cap | AZ. 309°51'± | 86.63' |

Signed by

Surveyor's Michigan License No. 23520

LIBER 004 PAGE 322



FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 26, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983