

COMMISSION
For corners in

Allegan County Remonumentation
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

Allegan (County)	Located In:	Corner Code #
1. Public Land Survey	T <u>4N</u> R <u>13W</u>	<u>A-13 (SW, 31)</u>
	T <u>3N</u> R <u>13W</u>	<u>Salem Twp.</u>
	T <u>4N</u> R <u>14W</u>	<u>Monterey Twp.</u>
2. Property Controlling in Section	S <u>4N</u> R <u>14W</u>	<u>M-13 (SE, 36)</u>
	S <u>4N</u> R <u>14W</u>	<u>Overisel Twp.</u>
3. Miscellaneous Property in Sec.	S <u>4N</u> R <u>14W</u>	<u>M-1 (NE, 1)</u>
	S <u>4N</u> R <u>14W</u>	<u>Heath Twp.</u>

1993 DEC 17 PM 1:56
REGISTER OF DEEDS
ALLEGAN COUNTY, MICHIGAN
James L. Carter

FILED

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, John C. Bueche, in a field survey on October 26, 19 93,
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules theretofore as required in the
current manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a
Court of Law; established, re-established, monumented, re-monumented, recovered, found as
expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.

A	B	C	D	E	F	G	H	I	J	K	L	M
2												
3												
4												
5												
6												
7												
8												
9												
10												
11												
12												
13												

A. Description of original monument and accessories and/or subsequent restoration:

A-13 corner common to 4 Twps.	3/4" pipe 12-12-81
1" pipe 1968	VanOrder Survey
TP NE 53.4'	40" Maple SE 67.9'
34" Maple SE 66.6'	C/L gas marker post NE 59.2'
St. sign SW 42.4'	NW cor. tel. pedestal SE 91.0'
TP SSE 91.0'	PP SW 96.05'
2472.04' E to S 1/4	3/4" pipe 8-29-91
31, 4-13	VanOrder Survey same wit. as above

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

A-13 Found 1" x 30" iron in bit. road @ surface	40" Maple SE 67.9'
34" Maple SE 66.6'	C/L gas marker post NE 59.2'
Meas. E to S 1/4 31, 2472.74'	NW cor. tel. pedestal SE 91.0'
Meas. E to N 1/4 6, 3-13, 2439.74'	PP SW 96.05'

And is accepted as a careful and faithful perpetuation of the
position of the original corner

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
A-13 Replaced 1" iron with Std. Allegan Co. Mon. (3/4" x 24" rod & cap)
Conc. Nail & Allegan Tag in NE side 12" Maple N 40° W 56.67'
C/L 2" gas pipe marker N 75° E 59.15'
Conc. Nail & Allegan Tag in W side 16" Pine S 30° E 68.88'
Conc. Nail & Allegan Tag in W side dbl. 14" Pine S 15° E 83.45'
Conc. Nail & Allegan Tag in SE side PP S 50° W 96.05'
On C/L bit. E-W
C/L gravel N is W 5'±
C/L gravel S is W 12'±
Meas. by hand

Signed by John C. Bueche
Surveyor's Michigan License No. 13027

Date Oct 26, 1993



FORM APPROVED BY MICHIGAN BOARD OF LAND SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1978
REVISED JAN., 1993

LIBER 004 PAGE 232