

RECEIVED

FILED

MAR 07 2000

ALLEGAN COUNTY REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE

FEB -1 AM 8:41

Filing Requirement of Act 74, Mich. P.A. 1970

SECTION

For corners in

Allegan  
(County)

Located In:

Corner Code #

1. Public Land Survey

T4N R16W

G-11

T R

T R

T R

NE corner

Section 33

Laketown Twp.

2. Property Controlling  
in Section

S T R

S T R

3. Miscellaneous  
Property in Sec.

S T R

S T R

4. Lot No. , Recorded Plat

5. Private Claims

I, Steve Lampen, in a field survey on January 25, 1999, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

G-11 W & W - 1904 L.C.R.C., L3, P161, Ratekin - 1977  
GLO - Brookfield - 1831 Well point Set 1/2" pipe over found 1 1/2" pipe with stones around  
Set post Nail in NW side 14" Pine N 70° E 92.23  
Beech 20 N 32 E 13 W & W - 1949 Nail in SW side 14" Maple N 25° W 35.52  
Hemlock 4 S 22 W 17 1 1/2" square iron Nail in SW side 30" Maple N 65° W 43.39  
Nail in W side 6" Maple S 10° E 22.54  
Old County Records Ratekin - 1965 Street sign N 10° E 18.66  
Show stone at corner 1 1/2" pipe 1 1/2" Square iron N 9° W 11.8  
Well point S 80° W 13.5  
T. O. Williams - 1892 1 1/2" pipe S 12° W 8.0  
Found small stone over remnants of old stake  
set iron and stones See Reverse

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

G-11 Found 1/2" pipe over 1 1/2" pipe with stones around. Nail in SW side 14" Pine N 70° E 92.23  
Nail in SW side 14" Maple N 25° W 35.52 Nail in SW side 30" Maple N 65° W 43.39  
Nail in W side 6" Maple S 10° E 22.54 Well point S 80° W 13.5 1 1/2" Pipe S 12° W 8.0  
N 35° W 35.62 16-D W side 14" Maple N 55° W 45.48 16-D W side 24" Maple  
S 15° E 22.43 16-D W side 10" Maple N 70° E 92.37 16-D N side 16" Pine

Replaced 1/2" pipe with an Allegan County Remonumentation iron and cap and accepted it as a careful and faithful perpetuation of the position of the original corner.

G-11 was approved by the Allegan County Remonumentation Peer Group on November 9 1999

APPROVED REMONUMENTATION CORNER

P.A. 345 OF 1990

ALLEGAN COUNTY

DATE APPROVED Nov. 9, 1999

COUNTY REP. [Signature]

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G-11 Allegan County Remonumentation iron and cap  
Azimuth = Michigan State Plan grid direction  
Remonumentation tag in N side power pole 98° 43' 77.45  
Remonumentation tag in NW side 16" Pine 63° 22' 92.25  
Remonumentation tag in E side 14" Maple 333° 29' 35.41  
Remonumentation tag in NW side 8" Maple 223° 05' 32.98  
1 1/2" pipe 192° 08' 7.92  
Well point 260° 31' 13.45

Signed by Steven Lampen

Date DECEMBER 31, 1999

Surveyor's Michigan License No. 37279

FF

MAR 07 2000

SECTION

LIBRO 007 PAGE 321

A. Continued

L.C.R.C., L5, P 338 - Brintnall - 1996  
Found 1/2" pipe with stones around  
N 35° W 35.62 16-D W side 14" Maple  
N 55° W 45.48 16-D W side 24" Maple  
S 15° E 22.43 16-D W side 10" Maple  
N 70° E 92.37 16-D N side 16" Pine  
West 5.55 centerline fence post