

ALLEGAN COUNTY REMONUMENTATION
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
Allegan
COMMISSION

(County)

Located In:

Corner Code #

1. Public Land Survey

4N 16W

G-13 (SW Sec 34)

Laketown Twp.

2. Property Controlling
in Section

S T R

3. Miscellaneous
Property in Sec.

S T R

4. Lot No. , Recorded Plat

5. Private Claims

1993 DEC 30 PM 2:42
REGISTER OF DEEDS
ALLEGAN COUNTY, MICH.
FILED

Register of Deeds Stamp & File Number

I, David R. Greer, in a field survey on December 6, 1993,
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the
current manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a
Court of Law; established, re-established, monumented, re-monumented, recovered, found as
expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Recorded in Liber 4, Page 53, May 3, 1989

G-13

Set 1/2" Iron & Cap

Centerline 3" Pipe (end Fe post)

P.K. SE Side 13" Poplar

P.K. N Side 2" Pine

1/2" Iron w/cap (NW cor Sec. 3)

WNW

52.05'

NNE

62.70'

ESE

50.17'

E

20.00'

G-13

Government Notes 1831

Post

Unknown Tree 8" N50 1/2°W 4.63 chkn

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

G-13

Found 1/2" iron with cap and accepted it as a careful and faithful perpetuation
of the position of the original corner

Centerline 3" Pipe (end Fe post)

P.K. SE Side 13" Poplar

P.K. N Side 2" Pine

1/2" Iron w/cap (NW cor Sec. 3)

WNW

52.05'

NNE

62.70'

ESE

50.17'

E

20.00'

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G-13

Replaced 1/2" Iron with Allegan County Remonumentation Iron & Cap

A.C. Remon tag & nail in S Side 10" Pine

Centerline 3" Pine, S End Fence

P.K. SE Side 13" Poplar

P.K. N Side 2" Pine

G-1 T3N, R16W, (remon)

N80°W

59.50'

N70°W

52.06'

N20°E

62.70'

S70°E

50.17'

E

20.00'

Signed by

Date 12/14/93

Surveyor's Michigan License No. 16042



W:\Deeds\Surv\Remon.doc

LIBER 004 PAGE 280

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 26, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983