1996 Alpena County Remonumentation Corner

MAY 1 S 1027

_____, Recorded Plat_

5. Private Claims _

as expressed below:

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Alpena (County)		Located In:	Corner Code #
1. F	Public Land Survey	T <u>29N</u> R <u>8E</u> T R	E-13
		T R	
		T R	
2. 1	Property Controlling	S T R	<u></u>
į	in Section	S T R	<u></u>
3.1	Miscellaneous	ST R	
ı	Property in Section	S T R	·

STATE OF MICHIGAN County of Alfena Recorded 10-17-1996 11:47:40 Kathy J. Matash REGISTER OF DEEDS

Liber 00002 Page 0067

Register of Deeds Stamp & File Number

١.	Daniel	т.	Kibba a field survey on _	July 1	, 19 <u>96</u> ,
do	hereby certify	that u	nder requirements of P.A. 74, I	Michigan P.A. of 1970, the	e comer points mentioned
in I	lines 1 and 2 a	bove w	ere in conformance with regul	ations and rules therefore	as required in the current
ma	anual of surve	ey inst	tructions of the United Stat	es Department of the I	Interior, Bureau of Land
			ecree of a Court of Law and/o		
E -	ahova wara in	confo	rmance with the rules of the l	Michigan Board of Profe	ssional Survevors or by a

Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

<u>A</u>	B	С	D	Ε	F	G	H	J	K	L M
2		-] 5		ļ_		-3	2		
-3-			<u> </u>	<u> </u>	1	4	4		4	\sqcup
4_	-¦	 -	ļ 	╀	ا و	4-	-10	<u> </u>	+	12-
5	+-			┼	╀-	+	+	\vdash	+	-
6	-18	1	ļ-	╁	16	+-	-15	14-	┿	13-
7	+	╁	├	┼	╀	+			+-	+
8	-19	+-2	ю—	+	21-	╁	-22	23-	+	24
9-		†	┢	+-	╁	╁	+		+-	-
10	-зо́ I	$+^{2}$	9— ∫	\dagger	28 	+	27-— 	-26- 	十	25—
11		1	 	T	†	T	1		1	<u> </u>
12	-31-	<u> </u>	32 		33- 	1	34—	35		36

A. Description of original monument and accessories and/or subsequent restoration:

1839: GLO Survey by Lewis Clason - set post & referenced: Hemlock 12 - N 76 E - 36 Hemlock 15 - N 41 W - 11.

1889: County Survey by Fred A. Rice - plain corner.

1976: Survey by Dave Guthrie - set ½" iron & referenced.

1980: Survey by Duane MacNeill - set 1" pipe & referenced.

1987: Survey by Earl Lewis - referenced existing 1" pipe.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1996: Found 1" pipe located 1' S. of C/L Hurbert Rd. and 17' W. of C/L Carriveau Rd. (to N.) and LaBonte Rd. (to S.)

This corner position is compatible with county and local surveys. This corner position is accepted as a careful and faithful perpetuation of the position of the original corner.

> P.A. 345 ALPENA COUNT PEER APPROVED 7/W/90

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1996: Placed 3" Alpena County cap stamped to identify the corner over 1/2" iron rod inside existing l" pipe, 6" below grade. OF LICE Referenced:

East - 13.25' - Fd. 1" pipe

N 22° W - 32.58' - Set N/Tag over flagged nail in Power Pole

N 55° E - 50.90' - Set N/Tag in fence post

N 58° E - 58.5' - Center of GTE marker post

S 20° W - 34' - Fd. N/Tag in old corner fence post lying flat

S 30° W - 36.48' - Fd. flagged roofing nail in fence post

_ Date _ October 15, 1996

Signed by_ Surveyor's Michigan License No. 37278

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYOR REVISED MAY 14, 1975

DANIEL T.

KIRBE

LAND

SURVEYOR

Mo.

37278

REVISED JAN., 1963