

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
Alpena

Located In: Corner Code ##

1. Public Land Survey

T 30N R 07E
T 30N R 06E
T R
T R

A8
N08
2. Property Controlling
in Section

S T R
S T R
3. Miscellaneous
Property in Sec.

S T R
S T R
4. Lot No.

Recorded Plat
5. Private Claims

JUN 17 10 58 AM '96
Kathy G. Matash
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

I, Earl T. Lewis, in a field survey on April 10, 1996,
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the
current manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a
Court of Law; established, re-established, monumented, re-monumented, recovered, found as
expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.

- A. Description of original monument and accessories and/or subsequent restoration:
- 1839: Lewis Glason

Set corner. Witnesses given: Maple 9 S 33° W 26, Beech 13 N 25° W 45
- 1885: W. Mirre

Set 4" sq cedar stake with a piece of iron from a plough, some tin cans, and an axe.
- 1905: J. McNeil

Found old stake. Set new cedar stake. No witnesses given.
- 1982 & 88: E. T. Lewis

Found 1/2" rod. Witnesses given: N 45° E 53.47' Telephone Pole, S 45° W 65.86' Power Pole
- 1991: T.L. Fabis, P.S.

Found 1/2" rod in mon. box. Wit. given: S30°W 58.75' P.P., S32°E 56.07' Anchor Pole, N66°E 72.59' S'ly Sign Post, N48°W 82.94' S.E. Cor. Pump Island
- 1995: T.L. Fabis, P.S.

Found 1/2" rod in mon. box. No witnesses given.
- 1995: G. St. Charles

Recorded cor. in Libr 2 of Cors, pg 12. Fd 1/2" rebar in mon box. Wit given: N40°E 61.18' Tag on Telephone Pole, S25°E 56.12' Tag on Anchor Pole, S40°W 58.75' Tag on Power Pole
- Unknown: Alpena Rd Comm

Fd 3/8" rod. Wit. given: N40°E 61.18' Tag on T. Pole, S25°E 56.12' Tag on Anchor P., S40°W 58.75' Tag on P.P.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- 1996:

Found 1/2" rerod.

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

SURVEY &
REMONUMENTATION

JUL 23 1996

COMMISSION

P.A. 345 ALPENA COUNTY
PEER APPROVED 5/5/96
D.L.B. Gm

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- 1996:

Placed appropriately stamped Alpena County Remonumentation 3" aluminum cap on existing 1/2" rerod in monument box.
- Witnesses given:

N 66° E 72.25' S'ly Sign Post
N 48° W 81.70' S.E. Cor. of Pump Island
S 40° E 55.25' Anchor Pole
S 40° W 58.10' Power Pole
N 45° W 112.50' Steel Pole



Signed by Earl T. Lewis Date June 12, 1996
Surveyor's Michigan License No. 27452