

JAN 25 2001

2000 Alpena County Remonumentation

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

SECTION

For corners in
Alpena

(County)

Located In:

Corner Code #



L- 2 P- 316

08/14/2000 10:20A

Page: 1 of 1

Kathy J. Mataash, Register Alpena Co., MI LDC 9.00

1. Public Land Survey

T 30N R 07E

E-6

2. Property Controlling
in Section

S

T

3. Miscellaneous
Property in Sec.

S

T

4. Lot No. , Recorded Plat

5. Private Claims

I, Wayne T. Lewis, in a field survey on 2-24-00, XX do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:
1839: Lewis Clason mark 14" Cedar for post, no witnesses.
1888: W. H. LeRoy established corner and witnessed.
1979: D. R. MacNeill, P.S. set 1" pipe and witnessed.
1979: R. S. Scott Assoc. (D. B. Guthrie, P.S.) found PK nail, and witnessed.
1997: Wilcox & Assoc. found 1" pipe, 2' West of C/L, found PK nail, 4.2' N'ly, no witnesses given.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
Found PK 2' West of King Settlement Road C/L and 5' South of Diamond Road and in line with fence to the East.
This corner position is accepted as a careful and faithful perpetuation of the position of the original corner.

P.A. 345 ALPENA COUNTY
PEER APPROVED 7-12-2000
D.A.R. K

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
2000: Placed 3" Alpena County Remonumentation Cap, stamped to identify the corner, on 1/2" rod in monument box in place of p.k. nail.

Witnesses:
S 85° E 46.49' Fence Corner (set tag #41922 over disk and nail)
South 4.22' 1-1/4" pipe w/cap unidentifiable
S 45° W 94.68' 8" Cedar (set tag #41922 in N'ly tree of cluster
S 75° W 51.82' P. Pole (set tag #41922 over large disk and nail)
N 40° W 67.37' Fence Corner Post (set tag #41922)



Signed by Wayne T. Lewis
Surveyor's Michigan License No. 41922

Date August 14, 2000