

SURVEY & REMONUMENTATION

NOV 16 1998

1998 Alpena County Remonumentation

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Liber 000002 Page 0172

For corners in

Alpena

(County)

Located In:

Corner Code #

1. Public Land Survey

T 32NR 06E

T 32NR 05E

T R

T R

T R

T R

T R

T R

2. Property Controlling
in Section

S

T R

S

T R

3. Miscellaneous

S

T R

Property in Sec.

S

T R

STATE OF MICHIGAN

County of Alpena

Recorded

10-08-1998 09:58:14

Kathy J. Matash

REGISTER OF DEEDS

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

I, Wayne T. Lewis, in a field survey on 5-19, 1998 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1857: GLO, Josiah Knauer, D.S. - set post & witnessed

1889: William H. Leroy, C.S. - found 3" square cedar stake

1913: William H. Leroy, C.S. - set 1-1/4"x3' gas pipe on West side of found stake

1915: Joseph W. McNeil, C.S. - found gas pipe beside stake

1997: Wayne T. Lewis, P.S. - set 1/2" rerod w/cap #41922, using County Surveyor's notes; corner falls 5.5' South of C/L of Long Rapids Road & 3' East of C/L of Salina Road; & witnessed

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1998: Found 1/2" rerod w/cap #41922; corner falls 5.5' South of C/L of Long Rapids Road & 3' East of C/L of Salina Road

This corner position is accepted as a careful and faithful perpetuation of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1998: Placed 3" Alpena County cap, stamped to identify the corner, on existing rerod in monument box.

Witnesses:

N 32° E 51.50' Guy Pole

S 56° W 74.08' Power Pole

S 37° E 68.03' Power Pole

S 37° W 59.50' Power Meter Conduit

P.A. 345 ALPENA COUNTY
PEER APPROVED 8/10/98

W.T. Lewis

Signed by Wayne T. Lewis

Date September 19, 1998

Surveyor's Michigan License No. 41922

