LEER 1 PAGE 274

DEC 1 0 1993

1928/Alpena County Remonumention Corner

007738 RECORDED ALPENA COUNTY MT.

LAND CORNER RECORDATION CERTIFICATE

iling	Requirement	of	Act	74,	Mich.	P.A.	1970

Fo	or corners in	t inng Hedane	and the contract of the contra	Dec 7 9 20 AM '93
	Alpena County)	Located In:	Corner Code ##	Maingo a Johnston
1.	Public Land Survey	T <u>32N</u> R <u>8E</u> T R T R T R	F-7	REGISTER OF DEEDS
2.	Property Controlling	S T R		
3.	in Section Miscellaneous Property in Sec.	S T R S T R S T R		Register of Deeds Stamp & File Number
		Recorded Plat		A B C D E F G H I J K L

I. Daniel T. Kibbe , in a field survey on July 1 , 19 93 , do nereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

	A	В	С	Ð	Ε	F	G	Н	1 1	K	_L	М
2		6	L	5	$oldsymbol{ol}}}}}}}}}}}}}}$	4		3	_	Ĭ	_	
3	L	$oldsymbol{\perp}$	(·		<u> </u>	1_	<u> </u>	1_	<u> </u>		لــــا	
4	L	ļ 7—	L	8	L	9	$oldsymbol{\perp}$	 10	1	1	1	2
5	L	丄	L	1_	1	_	1_	1_	<u></u>		<u> </u>	
6	L	 18—	<u> </u>	 17—	-	 16	┿	 15	 	4	1	3-
7	L	<u> </u>	↓_	Ļ.	_	♣	_	_	<u> </u>			
8	L	 19	↓_	 20	\vdash	 21	1	/ 22—	-2	3—	<u>2</u>	4
9	L	_	L	_	_	1_	_		L			_
10	L	30—	↓_	 29—	1	 28	\downarrow	 27	<u> </u> -2	6		5
11	<u></u>	丄	1_	\perp	1_	┸	1		<u> </u>	.	<u> </u>	
12	L	31	 	 32	\downarrow	33	\downarrow	34-	 	 5	<u> </u> 3	6
13	L	_	$oldsymbol{\perp}$	1		1			<u></u>	<u> </u>		L

- A. Description of original monument and accessories and/or subsequent restoration:
 - 1885: G.L.O. Re-survey by Josiah Knauer set post and referenced: Beech 18 N32 1/2E 53 / Beech 8 S56W 12.
 - 1887: County survey by Fred A. Rice Found G.L.O. corner and referenced.
 - 1890: County survey by Wm. H. LeRoy Found G.L.O. corner and referenced.
 - 1981: Survey by Duane MacNeill Set PK and referenced.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
 - 1993: Found PK nail 6.7' South of the Center of Lacomb Road. This corner position is compatible with former county surveys and is a reference for local surveys. It appears to be the best evidence of the corner position.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: 1993: Set 1/2" x 18" iron rod with 3" aluminum cap stamped to identify the corner.

Referenced:

N40°W - 12" Ash - 74.90 feet

S58°W - 16" Maple - 110.82 feet

N22°E - 5" Cedar - 55.82 feet

S15°E - NW corner hse #1497 - 90.93 feet



Signed by	D	îned t	T.	Liffe

Surveyor's Michigan License No. _

_ Date __<u>November 24, 1993</u>