

DEC 10 1993

LIBEX

1 PAGE 271

007735

1993 ALPENA COUNTY REMONUMENTATION COMMISSION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED
ALPENA COUNTY MI.

For corners in

Alpena
(County)

Located In:

Corner Code ##

1. Public Land Survey

T 32N R 8E

G-5.2

T R

T R

T R

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous
Property in Sec.

S T R

S T R

Other #16

DEC 7 9 20 AM '93

REGISTER OF DEEDS

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat

5. Private Claims

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Daniel T. Kibbe, in a field survey on July 1, 1993, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1855: G.L.O. Re-survey by Josiah Knauer - set meander post and referenced:
Hemlock 8 - S45 1/2W - 8 / W. Cedar (double) 16 - S82 1/2E - 13 1/2.
1988: Survey by David Guthrie - Found existing angle iron and referenced.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1993: Found 2" angle iron 0.5' deep, 10' South of south shore Long Lake. This corner was supported by testimony by neighbor Harry Wagner who stated that the angle iron has been the corner for the 40+ years that he has been there. The corner is compatible with the 1855 G.L.O. survey and is a reference for local surveys.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1993: Set 1/2" x 18" iron rod with 3" aluminum cap stamped to identify the corner.
Referenced:
S80°W - 22" Ash - 37.80 feet
S82°E - 16" Cedar - 59.63 feet
S18°W - 7" Spruce - 25.42 feet
S55°E - NW corner hse fnd. - 62.50 feet



Signed by Daniel T. Kibbe

Date November 24, 1993

Surveyor's Michigan License No. 37278