

# LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:  
Alpena  
(County)

Located In

Corner Code #

1. Public Land Survey	T	32N	R	8E	K-4
	T	32N	R	8E	J-4
2. Property Controlling in Section	S	T	R		
	S	T	R		
3. Miscellaneous Property in Section	S	T	R		
	S	T	R		

4. Lot No: \_\_\_\_\_ Recorded Plat: \_\_\_\_\_

5. Private Claims: \_\_\_\_\_

I, Carl T. Kiiskila, in a field survey on January 19, 2000 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

**NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.**

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

K-4 GLO Josiah Knauer D.S., 1855  
Set quarter section post  
Wit: Sugar 14" S26°W 24 links  
Ironwood 6" N10°E 19 links

J-4 Supervisor's Plat of Frank Skatzka property prepared by James L. Scott R.L.S. #8318 in 1964 shows the center of section.

Pages 111 and 112 County Survey Notes November 1904  
Joseph McNeil found one original B.T. standing, set new cedar stake. Wit: Green Maple 15" S17°E 41.5 links

R.S. Scott Engineering November 1962 Certificate of Survey shows corner, no witnesses given.

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

K-4 Found 1/2" pipe fitting J. W. McNeil's and R.S. Scott Engineering surveys in section 11 and 12.

J-4 Re-established the center of section 11 from information recorded on the Supervisor's Plat of Frank Skatzka property.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K-4 1/2" pipe  
Wit: 12" Cedar S22°E 32.11'  
16" Cedar S27°W 37.67'  
14" Cedar N31°E 56.02'  
Utility pole N85°E 68.68'  
Centerline of East and West road North 1'±

J-4 Set 5/8" X 16" capped iron rod P.S. #33981  
Wit: 8" Basswood S38°E 42.33'  
Utility Pole N65°W 76.00'  
8" Maple S15°E 38.98'  
3/4" capped iron pipe P.S. #19237 N19°E 33.48'

Signed by:

Carl T. Kiiskila

Date:

12-10-03

Surveyor's Michigan License No.:

33981

