

FEB 18 1999

175
Liber 00003 Page 0031

SECTION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

ANTRIM COUNTY MI.
Register of Deeds
Recorded

12-21-1998 11:36:54

Wanda R. Conway
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

For corners in

ANTRIM

(County)

MILTON TOWNSHIP

Located In:

Corner Code #

1998 REMONUMENTATION

1. Public Land Survey

T.28N R.9W

Aux. Meander

T. R.

Cor. Btw.

T. R.

K-5 & K-4 N.

T. R.

Side Lake

S. T. R.

0001

2. Property Controlling
in Section

S. T. R.

S. T. R.

3. Miscellaneous

S. T. R.

S. T. R.

Property in Sec.

4. Lot No. , Recorded Plat

5. Private Claims

I, RICHARD J. KRAL, in a field survey on November 19, 1998 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

A.M.C. (Auxiliary Meander Corner, Btw. K-5 & K-4 on N. Side Lake: On line Secs. 11 & 12, T28N-R9W, Milton Township

1852, Gov't Re-survey, set one witness-meander corner West, 6 Lks (39.60') of K-5, on line of Secs. 11 & 14; & set one meander cor. South 50 Lks. (33.00') of K-5 on line Secs. 13 & 14; also set meander cor. North 3.0 Ch. (198.00') of K-5, on line Secs. 11 & 12, witness cor. acc.; W. Pine 36", N5°E, 6 Lks. (3.96') Birch 8", S75°W, 33 Lks. (24.78')
1927, Plat of Wabigama, by B.L. Caukin; recorded in Lib. 2, Pg. 28; set conc. mons., one at West 92.75' and one at North, 283.2' & West 37.7' of Cor.K-5 (in lake)
1982, Survey by M.C. Feindt; recorded in Lib. 395, Pg. 1046; set 5/8" re-rod at aux. meander cor. on line Secs. 11 & 12, N side lake South, 2372.84' from K-4; A.M.C. acc., 11" R. Pine, N64°W, 28.0'; 24" Oak, S50°W, 64.18'; 10" Twin Cedar, N40°E, 36.08'; SW cor. Gar. N19°E, 87.14'; Road Ends sign, N75°E, 4.7'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

A.M.C. (Auxiliary Meander Corner, Btw. K-5 & K-4 on N. Side Lake: On line Secs. 11 & 12, T28N-R9W, Milton Township

Fd. 1" iron rod, opp. CL asphalt road North; 20' North of North edge water
Pulled & replaced with Antrim County monument (Berntsen Model G-1 [30" Piston] with G-2 Cap).
Fd. nail in tag #16034 in NW side Twin 16" cedar, N38°E, 35.94' (R.36.08')
Fd. Road Ends sign post N73°E, 4.6' (R.4.7')
Fd. SW cor. gar. N16°E, 87.02' (R.87.14')
Fd. nail in tag #16034 in N. side 28" Oak, S50°W, 64.22' (R.64.18')
Fd. nail in tag #16034 in E. side 12" R. pine, N66°W, 27.94' (R.28.0')
Fd. bolt spike, S65°E, 0.20'
No G.L.O. witnesses were found.

Ratified by peer group
in accordance with
P.O. 345
Antrim Co. Chairman
Arthur L. Lemox
Nov. 18, 1998

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A.M.C. (Auxiliary Meander Corner, Btw. K-5 & K-4 on N. Side Lake: On line Secs. 11 & 12, T28N-R9W, Milton Township

Fd. 1" iron rod, opp. CL asphalt road North, 20' North of North edge water
Pulled & replaced with Antrim County monument (Berntsen Model G-1 [30" Piston] with G-2 Cap).
Fd. nail in tag #16034 in NW side Twin 16" cedar, N38°E, 35.94' (R.36.08')
Fd. Road Ends sign post N73°E, 4.6' (R.4.7')
Fd. SW cor. gar. N16°E, 87.02' (R.87.14')
Fd. nail in tag #16034 in N. side 28" Oak, S50°W, 64.22' (R.64.18')
Fd. nail in tag #16034 in N. side 12" R. pine, N66°W, 27.94' (R.28.0')
Fd. bolt spike, S65°E, 0.20'

Signed by Richard J. Kral 7
Michigan License No. 26460

Date 12-16-98 Surveyor's

