

# LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:

Antrim

(County)

Located In

Corner Code #

1. Public Land Survey	T	31N	R 6W	M-11
	T	31N	R 6W	M-10
2. Property Controlling in Section	S	T	R	
	S	T	R	
3. Miscellaneous Property in Section	S	T	R	
	S	T	R	

4. Lot No: Recorded Plat:

5. Private Claims:

I, Carl T. Kiiskila, in a field survey on December 6, 2006, do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

**NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.**

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

M-11 G.L.O. 1839 John Hodson set post corner to section 25 and 36. Wit: Lynn 10" S55°W 5 links  
Beech 24" N18°W 41 links

M-10 G.L.O. 1839 John Hodgson set quarter section post  
Wit: Cedar 24" S38°W 16 links  
Bl Ash 12" N80°W 19 links

July 1962 Ken Ostling R.L.S. #10068 set a 1" Pipe with 4" cap by proportional measurement.

Wit: 8" Maple S35°W 31.6'  
9" Maple N68°E 12.2'  
8" Elm N80°W 27.4'

June 1962 Ken Ostling R.L.S. #10068 set a 1" pipe with 4" cap by proportionate measurement.

Wit: 30" W. Pine Stump N40°W 21.1'  
4" Balsam S61°E 25.4'

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

M-11 Found a 1" pipe with a broken off aluminum cap as set by K.J. Ostling

M-10 Found DNR monument as set by K.J. Ostling.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M-11 Found a 1" pipe

Wit: 14" Maple N70°E 12.70'  
14" Maple S37°W 32.39'  
5" Maple S77°W 19.37'  
6" Maple N12°E 17.10'  
Centerline of two track West 5'±

M-10 Found DNR monument

Wit: 8" Spruce N59°E 19.11'  
8" Spruce N30°W 21.48'  
4" Spruce S78°W 21.37'  
5" Spruce S24°E 25.60'

Signed by:

Carl T. Kiiskila

Date:

2-15-07

Surveyor's Michigan License No.:

33981

