

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:

Antrim

Located In

Corner Code #

(County)

1. Public Land Survey -	T	31N	R	6W	K-11
	T	31N	R	6W	L-11
2. Property Controlling in Section	S		T		R
	S		T		R
3. Miscellaneous Property in Section	S		T		R
	S		T		R

4. Lot No: _____ Recorded Plat: _____

5. Private Claims: _____

I, Carl T. Kiiskila, in a field survey on December 6, 2006, do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6			5		4		3		2		1	
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

K-11 G.L.O. 1856 E.D. Atwater set post for corner of 25,26,35 and 36

Wit: Sugar 16 N26°E 27 links
Hemlock 20 S30 ½°W 6 links

L-11 G.L.O. 1856 E.D. Atwater set post for quarter section corner

Wit: Sugar 5 N16°W 21 links
Sugar 18 S21°E 28 links

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

K-11 Found 2" pipe with square bolt accepted by local land owners as being the section corner.

L-11 Re-established the south quarter of section 25 midway and online between section corners.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K-11 Found 2" pipe with square bolt

Wit: 7" Maple S15°W 8.75'
14" Beech S78°W 16.96'
10" Maple N01°E 20.60'
7" Maple S55°E 10.18'
N-S Fence West 5'±
Blue Carsonite Post North 1'±

L-11 Set 1" Pipe with standard DNR cap

Wit: 8" Maple S20°E 11.86'
8" Maple N61°E 37.25'
10" Maple N06°W 26.80'
9" Maple S42°W 33.61'
Blue Carsonite Post North 1'±

Signed by:

Carl T. Kiiskila

Date:

2-15-07

Surveyor's Michigan License No.:

33981

