

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:

Arenac

(County)

Located In

Corner Code #

1. Public Land Survey T 19N R 3E E3
2. Property Controlling in Section S T R
3. Miscellaneous Property in Section S T R

4. Lot No: Recorded Plat:

5. Private Claims:

I, Craig W. McVean, in a field survey on Aug. 24, 2005 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

E3 - GLO - Set Post - J. Mullett - 1846

W. Pine 18" N77°W 34 L.

Cedar 12" S49°E 20 L.

- CCC Notes - 1930's - Random E. 160 CH - Random Post

N. Random 80 CH - Set Random post

62 N. of E-W Line.

- MDOT Note - 1964 - No evidence of corner

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

E3 - Sec. Cor. common to Sec. 4, 5, 8 & 9 - No conclusive GLO or corner evidence found. Set 4" DNR Alum. Cap on 1" x 4' long galv. iron pipe by double proportion to GLO between fd. Consumer's position at 'C3', MDOT position at 'G3', Fd. 'E1' and reset S.J.E. Lucas position at 'E5'. Area is open intermittent swamp land. DNR Mon. accepted as a careful and faithful re-establishment of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E3 - 4" DNR Alum. Cap on 1" x 4' long galv. iron pipe.

North 18.68' to set 3/8" x 18" rebar

East 25.50' to set 24" long 'T' iron

S48°W 36.04' to set 3/8" x 18" rebar

S34°E 42.80' to set 1/2" x 30" rebar

Set Blue Carsonite Post 1' N.



Signed by:

Craig W. McVean

Date:

9/22/2005

Surveyor's Michigan License No.:

39088