

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga (County)	Located In:	Corner Code #
1. Public Land Survey	T R	
	T R	
	T R	
2. Property Controlling in Section	S 17 T 47N R 34W	9
	S 6 T 47N R 34W	8
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. _____, Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6			5		4		3		2		1	
3													
4	7			8		9		10		11		12	
5													
6	18			17		16		15		14		13	
7													
8	19			20		21		22		23		24	
9													
10	30			29		28		27		26		25	
11													
12	31			32		33		34		35		36	
13													

I, Stephan J. Szyszkoski, in a field survey on 9 08/20/12
8 08/21/12 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(9-Sec. 17) East 1/16 corner, Section 17. Not previously monumented.

(8-Sec. 6) West 1/16 corner, Section 6. Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(9-Sec. 17) Established the position for the corner midway and on a straight line between Quarter
corner 1308.99' east and the Center of Section 17 1308.99' west.

(8-Sec. 6) Established the position for the corner on a straight line between Quarter corner
1196.59' west and the intersection of 1/4 lines of Section 6 1328.81' east. The position is 18.01
chains east and 20.00 chains west, proportionate, of said corners, respectively.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(9) Set 1"IDx32" I.pipe with 4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
5" Bl. Spruce N63°E 24.2' mrkd "1/16S BT"
4" Bl. Spruce S11°E 14.4' do
5" Bl. Spruce S29°W 12.5' do
6" Bl. Spruce N30°W 13.45' do
Set sq'd Bl.Spruce post adjacent.

(8) Set 1"IDx32" I.pipe with 4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
7" Sugar N87°E 19.05' mrkd "1/16S BT"
8" Sugar S54°E 33.2' do
5" Sugar S72°W 2.9' do
13" Sugar N03°W 5.7' do
Set sq'd Cedar post adjacent.

Bearings are magnetic.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 01/02/2013

For the Michigan Department of Natural Resources, Forest Resources Division

