

**LAND CORNER RECORDATION CERTIFICATE**  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Baraga

(County)

Located in:

Corner Code #

**1. Public Land Survey**

T 47N R 34W

K10

T R

T R

T R

**2. Property Controlling in Section**

S 26

T 47N R 34W

11

S T R

**3. Miscellaneous Property in Sec.**

S

T R

S

T R

Register of Deeds Stamp & File Number

**4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_**

**5. Private Claims \_\_\_\_\_**

11 Aug 20 2001

K10 Aug 13 2001

I, Stephan J. Szyszkoski, in a field survey on \_\_\_\_\_, 19\_\_\_\_ do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

**NOTE:** Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

**A. Description of original monument and accessories and/or subsequent restoration:**

(K10) Quarter corner common to Sections 25-26. 1852: Established by L.B. Searles midway between Section corners 40.03 chains north and south. Set wood post. Fir 10 S48E 31 L, Fir 8 N50W 11 L.

(11-Sec. 26) Southwest 1/16 corner, Section 26. Not established in the original survey. \*\*\*\*\*Continued from Part C, below: The Easterly Witness corner is described as follows: Set 1"IDx32" iron pipe with 4" alum. MDNR tablet on the 1/16 line 648.00' east of the corner position. Blazed and scribed: 8" W.Spruce N03W 22.3', 5" W.Spruce N72E 7.4', 6" B.Spruce S72E 26.2', 7" B.Spruce S33E 17.2'. Trees scribed "WC BT". Bearings are magnetic. Distances are to notch in lower blaze.

**B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:**

(K10) The original post and accessories were not recovered. Reestablished the corner midway and on a line of mean true bearing between Section corners 2635.50' north and south. The position falls on the shoulder of Highway US141 3.9' SW of the edge of the pavement and 18.5' SW of the centerline as constructed. The monument was driven to refusal, the top being 4.5' below the surface of the gravel shoulder.

(11-Sec. 26) Established the corner at the intersection of straight lines connecting opposite 1/16 corners. The corner position falls under the surface of the Wet River impoundment and is not monumented. Established two witness corners: 1) 225.00' north of the corner and on the 1/16 line, and 2) 648.00' east of the corner and on the 1/16 line. Monumented both WCs with standard MDNR monuments. The northerly WC is described below, the easterly WC is described in a continuation of Part C, above.

**C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:**

(K10) 1"IDx32" iron pipe with 4" alum.

MDNR tablet. Blazed and scribed:

15" W.Pine S20W 85.5' 1/4S NBT"

10" Cedar S55W 76.5' do

13" Cedar S64W 80.6' do

Center of 3.5"x5.5" wood post with

"Tracey Creek" sign is S30E 397.4'

distant. Bearings are magnetic.

Distances to trees are to notch in lower blaze.

(11) The Northerly WC: Set 1"IDx32" iron

pipe with 4" alum. MDNR tablet, on the

1/16 line 225.00' north of the corner

position. Blazed and scribed:

6" B.Spruce N52W 25.7' "WC BT"

7" B.Spruce N16W 21.9' do

7" B.Spruce N26E 6.2' do

9" B.Spruce N60E 18.9' do

Set sq'd cedar post adjacent.

Continued above, in Part A.



Signed by

*Stephan J. Szyszkoski*

Date

10/24/01

Surveyor's Michigan License No.

33986

For the Michigan Department of Natural Resources - Office of Property Management