

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga	Located In:	Corner Code #
(County)		
1. Public Land Survey	T R	
	T R	
	T R	
2. Property Controlling in Section	S 4 T 47N R 34W	4
	S 4 T 47N R 34W	5
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. _____, Recorded Plat _____		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6			5		4		3		2		1	
3													
4	7			8		9		10		11		12	
5													
6	18			17		16		15		14		13	
7													
8	19			20		21		22		23		24	
9													
10	30			29		28		27		26		25	
11													
12	31			32		33		34		35		36	
13													

I, Stephan J. Szyszkoski, in a field survey on 4 10/21/2008 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(4-Sec. 4) Northwest 1/16 corner, Section 4. Not established in the original survey.

(5-Sec. 4) North 1/16 corner, Section 4. Not established in the original survey.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(4-Sec. 4) Established the corner at the intersection of straight lines connecting opposite 1/16
corners.

(5-Sec. 4) Established the corner on the N-S 1/4 line of Section 4 20.00 chains, proportionate to the
original record north of the Center of Section. The Center of Section is 1315.33' south and the
North 1/4 corner of Section 4 is 1270.61' north.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(4) Set 1"IDx32" I.pipe with 4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
7" Sugar N06W 4.15' mrkd "1/16S BT"
9" Sugar S46E 36.4' do
11" Sugar S44W 24.6' do
6" Sugar S84W 6.35' do
Bearings are magnetic.

(5) Set 1"IDx32" I.pipe with 4" alum. MDNR cap.
8" R.Maple N75E 1.9' mrkd "1/16S BT"
10" Sugar S18E 21.5' do
18" W.Pine S61W 25.9' do
12" Sugar N59W 16.1' do
Set sq'd cedar post adjacent.
Bearings are magnetic.

Signed by

Stephan J. Szyszkoski

Date

11/03/2008

Surveyor's Michigan License No.

33986

For the Michigan Department of Natural Resources, Office of Land and Facilities



FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 13, 1971

Revised May 14, 1975

Revised Jan., 1983

Revised Oct., 1995