

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga	Located In:	Corner Code #
(County)		
1. Public Land Survey	T R	
	T R	
	T R	
2. Property Controlling in Section	S 15 T 48N R 31W	14
	S 15 T 48N R 31W	H6
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16				14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 14 05/17/2010 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(14-Sec. 15) South 1/16 corner between Sections 14 and 15. Not established in the original survey.

(H6) Center of Section 15. Not established in the original survey.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(14-Sec. 15) Established the corner midway and on the Section line between Quarter corner 1315.38'
north and Section corner 1315.38' south. The Section corner falls in Coon Lake and is not
monumented. For the purpose of the establishment of this 1/16 corner, the position of Section corner
I7 was computed by double proportionate measurement to the original record between corners G7, J7,
I6, and I8. The position for the 1/16 corner falls on exposed granite. The monument is a 1"x10"
iron pipe with a 4" alum. MDNR cap and a 5/8"x9" rebar grouted inside, which rebar is grouted into a
3/4"x4" deep hole drilled into the granite.

(H6) Established the corner at the intersection of straight lines connecting opposite 1/4 corners.
The position for the corner falls at an inaccessible location and is not monumented. Established a
WITNESS CORNER on the E-W 1/4 line, 80.00' east of the corner position.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(14) Set 1"ID capped pipe as described in Part B.
Set measuring nail with MDNR tag in the side of:
5" Oak N44E 13.75' mrkd "1/16S BT"
9" W.Pine S85E 26.0' do
4" Maple S59E 16.4' do
4" Cedar N56W 7.15' do
Bearings are magnetic.

(H6) Set 1"IDx32" I.pipe with 4" alum. MDNR cap
as a Witness Corner 80.00' easterly of the corner
position and on the 1/4 line.
Set measuring nail with MDNR tag in the side of:
5" Spruce N11W 26.95' mrkd "WC BT"
3" Balsam N59E 6.7' do
6" Spruce S17W 20.9' do
4" Balsam S84W 15.45' do
Set sq'd Cedar post adjacent.
Bearings are magnetic.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 07/07/2010

For the Michigan Department of Natural Resources and Environment, Forest Management Division

