

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF—	LOCATED IN—	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 48 N. R. 33 W. XX	A 9 & A 11
2. PROPERTY CONTROLLING IN SECTION	N. S. R. E. W.	
3. MISCELLANEOUS PROPERTY IN SECTION	N. S. R. E. W.	
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND FILING NUMBER _____

I, **Arthur O. Enger** do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970 the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram—over) were, in a field survey on **November 11, 1971**, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

Corner A 9: Original post possibly found, and apparently found the rotted stump of one original BT, a Tamarack 7 S65E 50, from which many years ago an unknown party had set a 5" octagonal concrete monument with an unmarked brass plate.

Corner A11: Original post not found, but found the rotted stump of one original BT, a Tamarack 7 N61W 44. Found no subsequent monuments.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Corner A 9: Verified the stump as probably being an original BT from a small axe mark on a piece of overgrowth. Also found a very old 2"x2" wood post lying buried in the swamp peat, possibly the original post. Distance N to lake shore checks well. Therefore, perpetuated corner as found.

Corner A11: Verified the stump as being an original BT from a notched blaze with scribe marks "BT" visible. Placed corner at record bearing and distance from the BT.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Monuments for both corners: 1" I.D. x 36" iron pipe with 4" aluminum cap.

Witnesses for Corner A9: Tamarack 7 N45°E (mag.) 9.5 ft. "S19, NBT"
Tamarack 5 N19½°W (mag.) 12.4 ft. "S24, NBT"
Tamarack 5 S17°W (mag.) 20.7 ft. "S25, NBT"

Witnesses for Corner A11: Tamarack 10 N22°W (mag.) 11.5 ft. "S25, NBT"
Tamarack 10 N69°E (mag.) 22.7 ft. "S30, NBT"
Tamarack 9 S9½°E (mag.) 21.6 ft. "S31, NBT"

SIGNED BY _____ DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

(SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____

DATE _____

APPROVED AND SIGNED BY _____

CHIEF OF SURVEY SERVICE

Arthur O. Enger
MICIGAN REGISTERED LAND SURVEYOR
Arthur O. Enger

DATE

February 15, 1973

(SEAL)

Michigan Department of Natural Resources

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

13581