## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

_			
ኮበፐ	COL	ners	: In

Signed by

Baraga	_ Located In:	Corner Code #	37 · C	
(County)				
1. Public Land Survey	TR TR		,	
2. Property Controlling in Section	S 24 T 48N R 33W S T R	13 (GCDB 660320)	0	
3. Miscellaneous Property in Sec.	S 25 T 48N R 33W S T R S T R	3 (GCDB 600260)	×	
	corded Plat		Register of Deeds Stamp & Fil	
5. Private Claims				1 1 1 1 1
t Stophan t Smankashi .		/24/14	3 5 5 4 3 - 3 - 3 - 3 - 3 - 3 - 3 - 3 - 3 - 3	╀╾┇╾┼╾┆╌┤
1, Stephan J. Szyszkoski , in	n a field survey on 3 08, 74, Michigan P.A. of 1970, the corner p	/13/14 do hereby state	4 - 7 - 8 - 9 - 10	-1112-
above were in conformance with	regulations and rules therefore as require	ed in the current manual of survey	5	<del>                                     </del>
instructions of the United States	Department of the Interior, Bureau of La	and Management or by a decree of	6 -18 17 16 15	13-13-
the rules of the Michigan Board	corner points mentioned in lines 3, 4 and d of Land Surveyors or by a Decree	5 above were in conformance with	7 + + + + + + + + + + + + + + + + + + +	<del>                                     </del>
re-established, monumented, recov	ered, found as expressed below:	o. a court of Law, established,	9 19 20 21 22	23-24-
			10 30 29 28 27	36
	ners, all in the same town and range	, may be recorded	11	20 25
on this certificate.			12 31 32 33 34	35 36
A. Description of original m	nonument and accessories and/or s	rubcoguent venteurtien.	13 0.F.M	15 1 36 1 CM/C
The second of th	onament and accessories and/or s	subsequent restoration:	* STEPHAN	
	17		* SZYSZKO	4 J. 🚺 💆
(13-Sec. 24) Southeas	t 1/16 corner, Section 24	. Not previously monu	mented. LAND	
20			SURVEYON.	OR /
			33986	100
			33986 AND S	UR
(3-Sec. 25) North 1/1	.6 corner between Sections	25 and 26. Not previ	ously monumented.	
B. Description of corner evi	idence found and/or method appli	iod in rootoning on acceptablish	*	
	derice round and/or method appli	led in restoring of reestablish	ing corner:	
(13-Sec. 24) Establis connecting opposite 1	shed the position for the ./16 corners.	corner at the intersec	ction of straight lines	
		13.		
(3-Sec. 25) Establish corner 1315.83' north	ned the position for the con and Quarter corner 1315.	orner midway and on th	ne Section line between	Section
		1		
C. Description of monumen	t for corner and accessories estab	lished to perpetuate locating	the position of the corner:	
(13) Set 1"IDx28" T.n	pipe with 2" alum. MDNR ca	n (3) Cat 1870-0	OH T mine with on 3	
Set measuring nail wi	th MDNR tag in the side o	f: Set measuring	B" I.pipe with 2" alum. nail with MDNR tag in th	MDNR cap. side of:
14" Maple N73°E 16.75		3" B.Spruce No:	2°W 9.25' mrkd "1/16	S BT"
9" Sugar S83°W 13.6'	do	3" B.Spruce N5: 3" B.Spruce S6:	9~5 10.2' d 1°E 17.05' A	lo lo
12" Maple N42°W 17.25	do	3" B.Spruce N8	8°W 6.55' d	lo
Set sq'd cedar post a E= 7894841.265 N= 1	ajacent. 196041.660	Set sq'd cedar E= 7893615 705	post adjacent. N= 195263.378	
		2- 7033013.703	n- 190203.3/B	

Surveyor's Michigan License No. 33986

For the Michigan Department of Natural Resources, Forest Resources Division

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum).

Coord. Ref.=NGS PID RL1468: N= 199449.721 m. E= 7900600.011 m.

09/03/2014