

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga (County)	Located In:	Corner Code #
1. Public Land Survey	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S 36 T 48N R 34W	14
	S 36 T 48N R 34W	15
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, Stephan J. Szyszkoski, in a field survey on 01/31/2012 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(14-Sec. 36) South 1/16 corner between Section 36 T48N-R34W and Section 31 T48N-R33W. Not previously
monumented.

(15-Sec. 36) West 1/16 corner between Section 36 T48N-R34W and Section 1 T47N-R34W. Not previously
monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(14-Sec. 36) Established the position for the corner midway and on the Range line between Section
corner 1313.80' south and Quarter corner 1313.80' north. The position falls on a large rock. The
monument placed at this position was bent to follow the slope of the rock but the center of the
monument cap marks the position for the corner.

(15-Sec. 36) Established the position for the corner midway and on the Township line between Section
corner 1320.02' west and Quarter corner 1320.02' east. The monument installed at this position leans
approx. 0.2' westerly due to sub-surface rock but the center of the alum. cap marks the corner
position.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(14) Set 1"IDx32" I.pipe with 4" alum. MDNR cap
The center of the cap marks the corner position.
Set measuring nail with MDNR tag in the side of:
9" W.Pine N25E 19.1' mrkd "1/16S BT"
5" Maple S88E 20.05' do
7" Cedar S21E 14.45' do
4" Balsam N63W 18.05' do
Set sq'd cedar post adjacent.
Bearings are magnetic.

(15) Set 1"IDx32" I.pipe with 4" alum. MNDR cap.
Set measuring nail with MDNR tag in the side of:
11" Hemlock N18W 17.65' mrkd "1/16S BT"
13" Hemlock N80E 18.55' do
11" Sugar S07W 10.1' do
3" Balsam S03W 7.75' do
Set sq'd cedar post adjacent.
Bearings are magnetic.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 03/06/2012

For the Michigan Department of Natural Resources, Forest Resources Division

