

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga	Located In:	Corner Code #
(County)		
1. Public Land Survey	T R	
	T R	
	T R	
2. Property Controlling in Section	S 36 T 48N R 34W	8
	S 36 T 48N R 34W	PCC E. of K12
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 02/01/2012 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(8-Sec. 36) West 1/16 corner, Section 36. Not previously monumented.

(PCC E. of K12) A property controlling corner marking the position of the E-W 1/4 line of Section 36 on or near the easterly R/W line of Hwy US-141. Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(8-Sec. 36) Established the corner midway and on a straight line between Quarter corner 1317.27' west and Center of Section 36 1317.27' east.

(PCC E. of K12) Established the position for the corner on the E-W 1/4 line of Section 36, 565.15' east of K12 and 752.12' west of 1/16 corner #8 Sec. 36, on a straight line between them. The position is the intersection of said 1/4 line with the extension of a straight line passing through the two monuments placed by J.C.Kapelczak PS on the easterly R/W line of US-141 and shown on his survey drawing for the Statewide Public Safety Radio Communication system, dated March 8, 2000.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(8) Set 1"IDx32" I.pipe with 4" alum. MDNR cap.  
Set measuring nail with MDNR tag in the side of:  
11" Balsam N64E 8.05' mrkd "1/16S BT"  
12" Maple S76E 16.35' do  
5" Balsam S05W 22.8' do  
4" Sugar N74W 22.85' do  
Set sq'd cedar post adjacent.  
Bearings are magnetic.

(PCC) Set 1"IDx32" I.pipe with 4" alum. MDNR cap  
stamped "P.O.L. C--C S.36"  
Set measuring nail with MDNR tag in the side of:  
12" Maple N58E 5.6' mrkd "POL BT"  
13" Cedar S41E 19.9' do  
4" dbl Cedar S72W 38.65' do  
4" Balsam N40W 40.8' do  
Set sq'd cedar post adjacent.  
Bearings are magnetic.

Signed by Stephan J. Szyszkoski  
Surveyor's Michigan License No. 33986

Date 03/06/2012

For the Michigan Department of Natural Resources, Forest Resources Division

