CONS. 4047

## MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

## LAND CORNER RECORD

T\_49\_ NR\_34\_W

	<u> </u>	INT
DESCRIPTION OF CORN	ER Section corner 21 - 22 - 27 - 28	-
DESCRIPTION OF CORNE	ER MONUMENT_1" iron pipe with 4" trass car	. <b>-</b>
WITNESSES TO CORNER	R _ 7 - 17 - 59	-
	5" red pine N 9°, N 53 links. Worked "S21NBT"	
	6" red pine S 47°, E 11 links. Marked "527%5T"	

## DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR

**RESTORED.** Replaced corner as set by unknown surveyor. Found 1" iron pipe in place with old jack pine stump marked "FT" bearing S 45°, E 5 links. Found possible b. T. jack pine stump bottom with several old axe marks, bearing M 7°, E 82 links. Government notes indicate this to be 6° links. Corner witnessed with I. Stevens, District Porester.

Note: This extra bearing tree may have been marked in the examination of the Pay. in 1354 by A. B. Wood. Found several such bearing trees in twy.

SURVEYOR'S SEAL

SIGNED \_\_\_\_ Bildy D. suckler \_\_\_\_ DAT

REGISTERED LAND SURVEYOR

DATE 5-1-59\_ \_