

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga (County)	Located In:	Corner Code #
1. Public Land Survey	T 49N R 34W	Meander corner between E10-E11 south shore
2. Property Controlling in Section	S 28 T 49N R 34W	4
3. Miscellaneous Property in Sec.	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 4 11/26/12 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
Instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(MC E10-E11) **Meander corner on the South shore of Big Lake between Sections 28 and 29.** 1853 - Established by Francis Coleman, Deputy Surveyor, 14.47 chains north of Section corner E11. Set post. BT Y.Pine 12" S49E 187 links. 1958 - Billy D. Buckler RLS notes in LCRC of record: This corner was replaced as set by unknown surveyor. Found iron pipe with brass cap in proper position. Found Y.Pine bearing tree (green) bearing S49E 187 links in excellent condition. Scribe marks plain. Has been chopped out many years ago. Corner marked by 2" iron pipe with 3" brass cap. NBTs: 5" J.Pine S33E 21 links, 4" J.Pine N80W 6 links.

(4) **Northwest 1/16 corner, Section 28**, being the NE corner of Gov't Lot 3, Section 28. Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(MC) Found a 1/2" iron rod encased in a 5" dia. concrete cylinder, being the P.O.B. of the recorded plat "Big Lake Plat" recorded in Liber 2 of plats, page 59, Baraga County Records. The monument was found at record bearing and distance from the 1958 Buckler NBT Jack Pine S33E 21 links, which is now a standing dead stub. Distance south to E11 was found to be 911.14 feet (13.805 chains), platted as 912.31'. Accepted the monument as a careful and faithful perpetuation of the position of the original corner.

(4) Established the position for the corner at the intersection of straight lines connecting opposite 1/16 corners.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(MC) Found 1/2" iron rod in 5" dia. concrete cylinder. Set measuring nail with MDNR tag in the side of:
3" Oak S15°E 2.5' mrkd "MC NBT"
5" Maple S06°E 10.5' do
9" J.Pine N84°W 8.0' do
8" J.Pine N60°W 19.85' do
Set sq'd Cedar post adjacent.
E=7879393.211 N=204213.470

(4) Set 1"IDx32" I.pipe with 4" alum. MDNR cap. Set measuring nail with MDNR tag in the side of:
4" Oak N06°W 31.1' mrkd "1/16S BT"
6" Oak S86°E 34.25' do
10" Oak S10°E 36.25' do
4" Maple in clump N88°W 13.05' do
Set sq'd Cedar post adjacent.
E=7879823.718 N=205138.096

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum)

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 03/13/2013

For the Michigan Department of Natural Resources, Forest Resources Division

