

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga (County)	Located In:	Corner Code #
1. Public Land Survey	T 49N R 34W	G7
	T 49N R 34W	G8
2. Property Controlling in Section	T R	
	T R	
	T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
	S T R	
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

Register of Deeds Stamp & File Number

1	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 11/28/12 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(G7) **Corner common to Sections 15-16-21-22.** 1958 - Reestablished by Billy D. Buckler RLS at record distance from Section corners 1 mile north and south and swamp edges west and north. Set 1" pipe with 4" brass cap. 7" J.Pine N36W 21 links, 8" J.Pine N41E 79 links, 5" J.Pine S62W 42 links.

(G8) **Quarter corner common to Sections 21 and 22.** 1958 - Reestablished by Billy D. Buckler RLS midway and on line between Section corners. Set 1" pipe with 4" brass cap. 5" J.Pine N02E 57 links, 5" J.Pine S35W 59 links.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(G7) Found the 1958 monument in good condition and at record bearing and distance from the 1958 witness J.Pine N36W 21 links, found in good condition with scribing visible. Accepted same as a careful and faithful reestablishment of the position of the original corner.

(G8) Found the 1958 monument substantially at the record position and at record bearing and distance from the 1958 accessories, both standing dead stubs. Accepted the monument as a careful and faithful reestablishment of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(G7) Found 1"ID I.pipe with 4" brass MI Dept. of Conservation cap. Set measuring nail with MDNR tag in the side of:  
11" J.Pine N28°W 14.6' old scribing (1958 NBT)  
5" Spruce N13°E 15.7' mrkd "S15 NBT"  
6" J.Pine N59°E 6.95' do  
4" Spruce S81°E 7.9' "S22 NBT"  
3" Sq'd and scribed post adjacent.  
E=7881094.253 N=207094.843

(G8) Found 1"ID I.pipe with 4" brass MI Dept. of Conservation cap. Set measuring nail with MDNR tag in the side of:  
3" Spruce N23°W 50.9' mrkd "1/4S NBT"  
7" J.Pine N08°E 33.75' do  
5" J.Pine N50°E 61.2' do  
5" Spruce S29°E 63.3' do  
Set sq'd cedar post adjacent.  
E=7881067.845 N=206297.911

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum).

Signed by Stephan J. Szyszkoski  
Surveyor's Michigan License No. 33986

Date 03/13/2013

For the Michigan Department of Natural Resources, Forest Resources Division

