

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

| | | |
|------------------------------------|------------------|---------------|
| Baraga | Located In: | Corner Code # |
| (County) | | |
| 1. Public Land Survey | T R | |
| | T R | |
| | T R | |
| 2. Property Controlling in Section | S 27 T 49N R 33W | 9 |
| | S T R | (GCDB 460240) |
| | S 27 T 49N R 33W | 12 |
| 3. Miscellaneous Property in Sec. | S T R | (GCDB 440220) |
| | S T R | |
| 4. Lot No. , Recorded Plat | | |
| 5. Private Claims | | |

Register of Deeds Stamp & File Number

| | A | B | C | D | E | F | G | H | I | J | K | L | M |
|----|----|---|----|---|----|---|----|---|----|---|----|---|---|
| 1 | | | | | | | | | | | | | |
| 2 | 6 | | 5 | | 4 | | 3 | | 2 | | 1 | | |
| 3 | | | | | | | | | | | | | |
| 4 | 7 | | 8 | | 9 | | 10 | | 11 | | 12 | | |
| 5 | | | | | | | | | | | | | |
| 6 | 18 | | 17 | | 16 | | 15 | | 14 | | 13 | | |
| 7 | | | | | | | | | | | | | |
| 8 | 19 | | 20 | | 21 | | 22 | | 23 | | 24 | | |
| 9 | | | | | | | | | | | | | |
| 10 | 30 | | 29 | | 28 | | 27 | | 26 | | 25 | | |
| 11 | | | | | | | | | | | | | |
| 12 | 31 | | 32 | | 33 | | 34 | | 35 | | 36 | | |
| 13 | | | | | | | | | | | | | |

I, Stephan J. Szyszkoski, in a field survey on 07/22/15 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(9-Sec. 27) Center-East 1/16 corner, Section 27. Not previously monumented.

(12-Sec. 27) Center-South 1/16 corner, Section 27. Not previously monumented.



B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(9-Sec. 27) Established the position for the corner midway and on a straight line between Quarter corner 1318.40' east and Center of Section 27 1318.40' west. An East-West blue paint line was found to be 25 feet south of the corner.

(12-Sec. 27) Established the position for the corner midway and on a straight line between Quarter corner 1314.18' south and Center of Section 27 1314.18' north. At the corner position, a N-S blue paint line was found to be 11' west.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(9) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
11" Elm N18°W 17.05' mrkd "1/16S BT"
7" Sugar S54°E 34.35' do
10" Y.Birch S27°E 23.6' do
5" Sugar S13°W 22.1' do
Set sq'd cedar post adjacent.
E= 7891787.459 N= 204487.427

(12) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
8" Sugar N20°E 22.1' mrkd "1/16S BT"
7" Sugar S89°E 2.2' do
4" Ironwood S06°E 19.2' do
11" Sugar N70°W 11.9' do
Set sq'd cedar post adjacent.
E= 7891379.551 N= 204095.701

Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 datum.
Coord. Ref.=NGS PID RL0476: N= 196482.411 m. E= 7879234.516 m.

Signed by Stephan J. Szyszkoski Date 10/27/2015
Surveyor's Michigan License No. 33986

For the Michigan Department of Natural Resources, Forest Resources Division