

# LAND CORNER RECORDATION CERTIFICATE

Authority: 1970 PA 74, MCL 54.205

Surveyor's Name: Stephan J. Szyszkoski

Field Survey Date: See below

For corner(s) in: Baraga County

## Original Public Land Survey Corner

## Corner Code

a. S            T 49N R 33W L07 (GCDB 640400)  
b. S            T 49N R 33W K07 (GCDB 600400)  
S            T            R             
S            T            R           

## Property Corner

## 1/16 Corner Code

S            T            R             
S            T            R             
S            T            R             
S            T            R           



1	A	B	C	D	E	F	G	H	I	J	K	L	M	1
2		6		5		4		3		2		1		2
3														3
4		7		8		9		10		11		12		4
5														5
6		18		17		16		15		14		13		6
7											●	●		7
8		19		20		21		22		23		24		8
9														9
10		30		29		28		27		26		25		10
11														11
12		31		32		33		34		35		36		12
13														13
	A	B	C	D	E	F	G	H	I	J	K	L	M	

## Part A. Corner History

a.) Quarter corner common to Sections 13 and 24. 1852 - Established by Z.B.Searles, Deputy, midway and on the Section line between Section corners 40.00 chains east and west. Set post. Sugar 12" S47°E 31 links, Sugar 18" N35°W 27 links. 1943 - Norman T. Thompson RLS notes that he did not find the corner "No 1/4 cor. Just old frog on Sugar"

b.) Section corner common to Sections 13-14-23-24. 1852 - Established by Zelotes B. Searles, Deputy. Set post. Sugar 8" S29°W 30 links, Sugar 10" N54°E 15 links. 1943 - Notes of N.T.Thompson, RLS, state "Sugar BT S29°W OK. Set Bal. post. New BT Ironwood 6" N30°W 15.5', New BT Sugar 6" S55°E 11.2'".

## Part B: Surveyor's Report on Perpetuation, Restoration, Reestablishment, or Monumentation of Corner

a.) Sept. 27, 2017. The original post and accessories were not recovered. Found no evidence of the position of the original corner on the ground. Reestablished the position for the corner midway and on the Section line between Section corners 2634.66' east and west.

b.) Sept. 27, 2017. Found a 3/4" ID pinched iron pipe at record bearing and distance from the 1943 witnesses, now both stumps. The original BTs were not recovered. A Celotex Corp. location poster on a 12" Sugar N46°W 19' faces the pipe. Accepted the pipe as a careful and faithful perpetuation of the position of the original corner, removed it and, in its position, placed a new monument as described below.

## Part C: Field Evidence of Perpetuation or Monumentation of Corner

a.) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.  
Set measuring nail with MDNR tag in the side of:  
6" Sugar N75°E 11.0' mrkd "1/4S NBT"  
7" Sugar S27°E 25.25' do  
5" Sugar S12°W 21.95' do  
22" Sugar N33°W 15.1' do  
Set sq'd cedar post adjacent.  
E= 7894645.847 N= 206827.636

b.) Set 1"IDx28" I.pipe with 2" alum. MDNR cap Set  
measuring nail with MDNR tag in the side of:  
5" Sugar N38°E 9.15' mrkd "S13 NBT"  
4" Sugar S62°E 32.05' "S24 NBT"  
6" Sugar S25°W 20.7' "S23 NBT"  
12" Sugar N46°W 19.3' "S14 NBT"  
Set sq'd cedar post adjacent.  
E= 7893843.140 N= 206846.191

Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 datum.

Coord. Ref.=NGS PID RL0041: N= 210246.994 m. E= 7895426.985 m.

*Stephan J. Szyszkoski*

10/16/2017

Professional Surveyor's License No.: 33986

page 1 of 1

Prepared By: S.J. Szyszkoski for the Michigan Dept. of Natural Resources, 427 N. US41 Baraga, MI 49908