

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga (County)	Located In:	Corner Code #
1. Public Land Survey	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S 18 T 50N R 34W	8
	S 30 T 50N R 34W	10
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6	18			17		16		15		14		13	
7													
8	19			20		21		22		23		24	
9													
10	30			29		28		27		26		25	
11													
12	31			32		33		34		35		36	
13													

I, Stephan J. Szyszkoski, in a field survey on 8 05/30/13  
10 06/11/13 do hereby state  
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2  
above were in conformance with regulations and rules therefore as required in the current manual of survey  
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of  
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with  
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,  
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded  
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(8-Sec. 18) West 1/16 corner, Section 18. Not previously monumented.

(10-Sec. 30) South 1/16 corner between Section 30 T50N-R34W and Section 25 T50N-R35W. Not  
previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(8-Sec. 18) Established the position for the corner on a straight line between Center of Section  
1320.97' east (20.00 ch. GLO) and Quarter corner 1087.18' west (16.46 ch. GLO, derived), being  
proportionate to the original plat.

(10-Sec. 30) Established the position for the corner midway and on the Range line between Section  
corner 1317.03' south and Quarter corner 1317.03' north.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(8) Set 1"IDx32" I.pipe with 4" alum. MDNR cap.  
Set measuring nail with MDNR tag in the side of:  
3" Spruce N73°E 19.7' mrkd "1/16S BT"  
3" Spruce S12°E 16.25' do  
7" Balsam S40°W 23.45' do  
4" Spruce N49°W 1.85' do  
Set sq'd cedar post adjacent.  
E= 7876899.832 N= 217595.247

(10) Set 1"IDx32" I.pipe with 4" alum. MDNR cap.  
Set measuring nail with MDNR tag in the side of:  
3" Oak N24°W 12.3' mrkd "1/16S BT"  
9" Maple N24°E 29.2' do  
4" Oak S54°E 17.9' do  
5" W.Pine S36°W 28.8' do  
Set sq'd cedar post adjacent.  
E= 7876483.926 N= 213994.599

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum  
Coord. Ref.=NGS PID DI1837: N= 221257.624 m. E= 7884435.168 m.

Signed by Stephan J. Szyszkoski  
Surveyor's Michigan License No. 33986

Date 07/02/2013

For the Michigan Department of Natural Resources, Forest Resources Division

