

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga (County)	Located In:	Corner Code #
1. Public Land Survey	T R	
	T R	
	T R	
2. Property Controlling in Section	S 2 T 50N R 34W	15
	S T R	(GCDB 520600)
	S 2 T 50N R 34W	C-S-SE 1/64
3. Miscellaneous Property in Sec.	S T R	(GCDB 560510)
	S T R	
4. Lot No. _____, Recorded Plat		
5. Private Claims		

I, Stephan J. Szyszkoski, in a field survey on 12/15/15 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(15-Sec. 2) West 1/16 corner between Sections 2 and 11.
Not previously monumented.

(C-S-SE 1/64) Center-South-Southeast 1/64 corner, Section 2. Also being known as the NW corner of
the S1/2 of the SE1/4 of the SE1/4 of Section 2. Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(15-Sec. 2) Established the position for the corner midway and on the Section line between Section
corner 1317.62' west and Quarter corner 1317.62' east.

(C-S-SE 1/64) Established the position for the corner midway and on a straight line between 1/16
corner #16 659.78' south and the computed position for 1/16 corner #13 (intersection of 1/16 lines)
659.78' north.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(15) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
9" Y.Birch N78°W 14.1' mrkd "1/16S BT"
4" Balsam N26°W 9.65' do
9" Y.Birch N02°E 18.65' do
9" Y.Birch N62°E 33.85' do
Set sq'd cedar post adjacent.
E= 7883349.921 N= 219864.693

(1/64) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
5" R.Pine N62°E 14.45' mrkd "1/64S BT"
8" W.Pine S05°W 20.4' do
4" R.Pine S55°W 32.6' do
4" R.Pine N40°W 15.25' do
Set sq'd cedar post adjacent.
E= 7884156.772 N= 220055.592

Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 datum.
Coord. Ref.=NGS PID D08499: N= 221257.621 m. E= 7884435.168 m.

Signed by Stephan J. Szyszkoski Date 01/21/2016
Surveyor's Michigan License No. 33986

For the Michigan Department of Natural Resources, Forest Resources Division

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

