

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga (County)	Located In:	Corner Code #
1. Public Land Survey	T R	
	T R	
	T R	
2. Property Controlling in Section	S 16 T 52N R 30W	3
	S 16 T 52N R 30W	4
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 3 05/12/2011 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
Instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(3-Sec. 16) North 1/16 corner between Sections 16-17. Not established in the original survey.

(4-Sec. 16) Northwest 1/16 corner, Section 16. Not established in the original survey.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(3-Sec. 16) Established the corner 20 chains (1320.00 ft.) north of monumented Quarter corner E6 and
on the Section line between E6 and the recorded Witness Corner to the Meander Corner at the shore of
Lake Superior, 1228.82' north.

(4-Sec. 16) Established the corner at the intersection of straight lines connecting opposite 1/16
corners.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(3) Set 1"IDx32" I.pipe with 4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
9" Maple N36E 19.4' mrkd "1/16S BT"
6" W.Spruce N82E 24.4' do
12" Maple S29W 4.7' do
11" Maple N77W 16.65' do
Set sq'd Cedar post adjacent.
Bearings are magnetic.

(4) Set 1"IDx32" I.pipe with 4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
9" Sugar N79E 37.8' mrkd "1/16S BT"
6" Sugar S69E 19.85' do
4" Sugar S73W 14.5' do
4" Sugar N15W 12.15' do
Set sq'd Cedar post adjacent.
Bearings are magnetic. The monument leans
slightly south. The top center of the cap
marks the corner position.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 05/18/2011

For the Michigan Department of Natural Resources, Office of Land and Facilities

