

DEC 7 4 26 PM '93

Sandy Schondelmayer

REGISTER OF DEEDS

002130

BARRY COUNTY REMONUMENTATION
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Barry

(County)

Located In:

Corner Code #

1. Public Land Survey

T 1N R 7W

G-8

2. Property Controlling
in Section

S T R

3. Miscellaneous
Property in Sec.

S T R

4. Lot No. , Recorded Plat

5. Private Claims

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Daniel M. Ryan, in a field survey on September 8, 19 93, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

GL0: 16" White Oak, S70½°E, 13.00 feet
12" White Oak, N86°W, 26.00 feet

D. Hooth, 4/16/64: set 1-½" iron pipe
38" Maple, N35°E, 70.58 feet
Telephone pole, N55°E, 68.24 feet
30" Maple, due East, 36.62 feet

C. Pike, 3/16/73: Monument box
in line with East and West fence
7.4 feet West of the centerline of M-66

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found ½" iron in monument box.
7.5 feet, more or less, West of centerline of M-66.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
Found ½" iron in monument box, replaced with Barry county Remonumentation iron and cap.
Find P.K. on North side of Utility pole, N83°W, 58.31 feet.
Find P.K. on South side of Utility pole, N82°E, 63.45 feet.
Set 60p nail in East side of 6" Elm, N43°W, 59.84 feet.
Set 60p nail in East side of 8" locust, S26°W, 97.44 feet.

SURVEY &
REMONUMENTATION

APR 05 1994

COMMISSION



Signed by Daniel M. Ryan

Date September 8, 1993

Surveyor's Michigan License No. 34975