

SURVEY & REMONUMENTATION

SEP 14 1999

BARRY COUNTY REMONUMENTATION  
LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN  
COUNTY OF BARRY  
RECEIVED FOR RECORD

JUL 20 3 07 PM '93

Sandy Schondelmayer  
REGISTER OF DEEDS

002065

Register of Deeds Stamp & File Number

For corners in SECTION

BARRY

(County)

Located In:

Corner Code ##

MAPLE GROVE

1. Public Land Survey

T 2N R 7W

F-5

T R

T R

T R

2. Property Controlling  
in Section

S T R

S T R

3. Miscellaneous  
Property in Sec.

S T R

S T R

4. Lot No. , Recorded Plat

5. Private Claims

I, ROBERT R. CARR, in a field survey on DECEMBER 7, 1992, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

SURVEY BY SETH PRATT, DEPUTY CO. SURVEYOR, 1882  
STAKE  
ELM 8" N49°20'W, 83 LINKS  
ELM 4" S18°W 56 LINKS

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND IRON STAKE ACCEPTED AS PERPETUATION OF ABOVE.  
2' SOUTH OF CENTERLINE ROAD AND IN LINE WITH OLD FENCES  
TO NORTH AND SOUTH, NO WITNESSES REMAINING.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

REPLACED FOUND IRON STAKE WITH STANDARD BARRY CO. REMON. 3/4" ROD AND ALUM. CAP  
WITH CENTER PUNCH AND RECESSED IN PAVED SURFACE.  
1/2" IRON SOUTHERLY 33.00 FT.  
NAIL AND REMON. SPOTTER IN EASTERLY SIDE OF BLACK CHERRY. N08°E, 29.47 FT.  
NAIL AND REMON. SPOTTER IN SOUTHWESTERLY SIDE OF 6" WALNUT S42°E, 41.18 FT.  
IN LINE WITH FENCES RUNNING NORTH AND SOUTH.

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

Signed by

ROBERT R. CARR

Date

JULY 13, 1993

Surveyor's Michigan License No.

20704

