

BARRY COUNTY REMONUMENTATION
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN
COUNTY OF BARRY
RECEIVED FOR RECORD

DEC 14 8 54 AM '93

Sandy Schondelmayer
REGISTER OF DEEDS

002173

Register of Deeds Stamp & File Number

corners in

BARRY

(County)

Located In:

Corner Code #

Public Land Survey

T 2N R 9W

K-7

T R

HOPE

T R

T R

Property Controlling

S T R

in Section

S T R

Miscellaneous

S T R

Property in Sec.

S T R

Lot No. , Recorded Plat

Private Claims

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

BRIAN REYNOLDS in a field survey on NOVEMBER 9TH, 19 93, hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration:

CORNER ESTABLISHED BY G.L.O. DEPUTY SURVEYOR SYLVESTER SIBLEY UNDER CONTRACT DATED 5TH OCT., 1826. SET POST CORNER TO SECTIONS 13, 14, 23, 24.

AN ELM 8 S35W 35

A W. ASH 7 N28E 20

SURVEY BY CO. SURVEYOR WALTER HEATH OCT. 13-19, 1903. SECTION CORNER FD BY DIGGING, THE HOLLOW STUMP OF ONE U.S. BEARING TREE (WHITE ASH 7 N28E 20) AND FOUND REMAINS OF STAKE AT CORRECT POINT. SET 2" WELL PIPE.

WITNESSES: WHITE OAK 20 N23 1/4E 93 3/4

HICKORY 10 N40 1/2E 63

CONTINUED ON BACK

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FD 1/2" PIPE IN MON. BOX. PLACED BARRY CO. REMON. CAP ON EXISTING PIPE.

ACCEPTED THE FOUND 1/2" PIPE AS THE BEST AVAILABLE EVIDENCE OF THE CORNER POSITION.

SURVEY &
REMONUMENTATION

APR 05 1994

COMMISSION

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1/2" PIPE WITH REMONUMENTATION CAP IN MONUMENT BOX

40D NAIL & WITNESS TAG IN WEST SIDE 20" ELM N15°E 72.53'

40D NAIL & WITNESS TAG IN NORTH SIDE 12" ELM N74°E 34.65'

40D NAIL & WITNESS TAG IN WEST SIDE 14" ELM S28°E 58.98'

40D NAIL & WITNESS TAG IN NORTH SIDE 10" ELM S80°W 68.53'

40D NAIL & WITNESS TAG IN NORTHEAST SIDE 10" ASH N44°W 76.80'

Q. ROAD WEST 2.5'



igned by

Date

DECEMBER 7, 1993

urveyor's Michigan License No.

31602

"A" CONTINUED

BARRY CO. ROAD COMMISSION WITNESSES

IRON

12" HICKORY N41°E

20" WILLOW S88°E 25.8'

6" SASSAFRAS N26°W 64.4

14" ELM N40°E 42.1'

SURVEY &
REMONUMENTATION

APR 05 1994

COMMISSION

