LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74 Mich. PA 1970.

	i iiiig i toquiit	SITICITE OF ACE 14, WHICH	1 1370
For Corners In: Benzie	Located In	Corner Code #	1.
(County)			
1. Public Land Survey	T R		
Property Controlling in Section	S 24 T 25N R 14W	2	
Miscellaneous Property in Section	S 24 T 25N R 14W S T R	14	
	S T R		Register of Deeds Stamp & File Number
4. Lot No:	Recorded Plat:		A B C D E F G H I J K L M
5. Private Claims:			2 - 6 - 5 - 4 - 3 - 2 - 1
requirements of PA 74, Mi and 2 above were in confo the current manual of sur Interior, Bureau of Land Ma corner points mentioned in of the Michigan Board of	field survey on Oct. 21, 2013 do here chigan PA of 1970, the corner points a rmance with regulations and rules there in the vey instructions of the United States an agement or by a decree of a Court of lines 3, 4 and 5 above were in conform f Land Surveyors or by a Decree of monumented, recovered, found as exp	nentioned in lines 1 efore as required in Department of the Law and/or that the nance with the rules f a Court of Law;	3 4
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.			10 -30 -29 -28 -27 -26 -25
			11
			13
A. Description of original	monument and accessories and/o	r subsequent restoration	: n:
beam equidistant and corners.	o. 66 – F. S. Haswell – Planted iron d in right line between coterminous I & Associates – Field notes. Area tes).	pipe eq - 1981 ~ 1981 ~ (PS #10 \$0°44'5 1321.29 - 2001 ~ Jenema & 1322. - 2006 ~	CSR – L. 2, p. 66. F. S. Haswell – Drove 1 ¼" iron uidistant and in right line between 6 & 3. Record Survey L. 1, p. 707 – H. R. Bruning 10681) – Fd. 1 ¼" iron pipe set by F. S. Haswell – 1907 60"W 9' to 'M9'; N0°42'30"E 1324.38' to 'M8'. Unrecorded Survey – Jenema Land Survey – B. J. a (PS #25850) – Shows Calc. position 1322.85' to 'M9 84' to 'M8' B. J. Jenema field notes. Set rerod with cap. Falls in a. Fd. 1 ½" pipe 1 ½' S. (lying flat stood up)
B. Description of corner	evidence found and/or method app	lied in restoring or re-es	tablishing comer:
capped iron rebar #2 skidder 8' x 8'± dug o could find no evidence	on to Sec. 13 & 24, T25N, R14W – 8417 per Mitchell survey at S. Edge out area. Searched for Haswell iron the of it. ½" CIR accepted as the befithe position of the corner.	e of T25N, F but ground st but it wa River. T Bearing 1324.39 FSH, 13 in same N34°41' should a	Corner common to Sec. 24, T25N, R14W and Sec. 19813W – Fd. 1 ½" I.D. x 3.35' long iron pipe – ½ way in with slight lean – Plumbed up and tried to drive down as hitting something. Pipe in flood plain of Betsie The Centerline of Bit. Rd. is 58'± East. Measured Grid and distance N2°14'53"E 1324.01' (1321.98' – FSH, 8' – HRB) to 'M8' and S2°15'57"W 1321.35' (1321.98' B21.29' – HRB) to 'M9'. It appears this Haswell pipe is position (± 0.2') as Bruning found it in 1981. W 1.75' from the pipe found Jenema's ½" CIR. Felt I accept Haswell's historical pipe as found by Bruning at available evidence of the position of the corner.
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:			
S84°E 38.44' to set N	tamped 2" Alum. Cap on 5/8" x 34" N & T in S. side 28" S. Maple N & T in E. side 4" Oak	center o	Stamped 2" Alum. Cap on 5/8" x 4' long iron rebar into of Haswell's 1 ¼" x 3.35' long iron pipe. Pipe is Up

N54°W 25.76' to set N & T in NE side 7" Oak S45°W 30.25' to set N & T in NW side 6" Oak Set Blue Composite Post with Loc. tag 1' NE

Blue Composite Post 1' SW. S67°W 18.57'to set ½" x 18" rebar at edge of river bayou. S8°E 32.78' to set N & T in E. side 11" Elm

N51°E 27.64' to set N & T in SE side 7" Elm N34°41'W 1.75' to Fd. ½" CIR #25850

Surveyor's Michigan License No.: 39088

7/16/2014

FORM APPROVED BY MICHIGAN STATE BOARD OF

McVEAN PROFESSIONA SURVEYOR No.

28, 1971 Way 14, 1975 Vised Jan. 1983