

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

INLAND TOWNSHIP

For corners in  
BENZIE COUNTY  
(County)

Located In:

Corner Code ~~##~~STATE OF MICHIGAN  
BENZIE COUNTY  
RECORDED

22 JAN 1999 3:03:54 PM

MICHELLE R. GRAY  
REGISTER OF DEEDS  
# PAGES ONE

Register of Deeds Stamp &amp; File Number

1. Public Land Survey T 26N R 13W I-9  
T \_\_\_\_\_ R \_\_\_\_\_  
T \_\_\_\_\_ R \_\_\_\_\_  
T \_\_\_\_\_ R \_\_\_\_\_  
T \_\_\_\_\_ R \_\_\_\_\_
2. Property Controlling S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
in Section S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_
3. Miscellaneous S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
Property in Sec. S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_
4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_
5. Private Claims \_\_\_\_\_

I, John B. Smendzuik, in a field survey on December 1, 19 98, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

**NOTE:** Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

## A. Description of original monument and accessories and/or subsequent restoration:

J-7: 1837: GLO set post - Beech 14" N13°W 33 links and Beech 9" S12°W 4 links. 1905-1906: Guy Langford, Survey Record II, Page 50, cedar post 4x4 set by original witness trees. 1983: Bill Batzer, Certificate of Survey in Liber 1, Page 764, found 1" iron bar. 1980's: BCRC found 1" iron bar which fits Batzer witnesses. 1996-97: Michigan DNR section work, found 1" iron bar in east-west gravel road.

## B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

J-7 1998: Found 1"x 14" iron bar, 10" below grade of east-west road. The Benzie County Peer Group accepted the iron bar as a locally accepted corner.

Ratified by Peer Group  
In accordance with P.A. 345Chairman John B. SmendzuikDate 11/23/98

## C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

J-7: Pulled the iron bar and set a 3" diameter Benzie County Remonumentation Program concrete monument with a brass cap 6" below grade of east-west gravel road.

9" W. Birch S56°E 60.28' to found nail.

Gordon Bonney iron and cap South 32.95'.

9" W. Birch S12°W 33.47' to set nail and BCRP tag.

9" and 8" Twin Maple N58°E 71.93' to found old nail and set new nail and BCRP tag.

Monument is in the centerline of St. John's Road.

Signed by John B. Smendzuik Date 11/22/99Surveyor's Michigan License No. 30895