

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:

Benzie

(County)

Located In

Corner Code #

1. Public Land Survey

T

R

2. Property Controlling
in Section

S 10

T

26N

R 14W

5

S 10

T

26N

R 14W

6

3. Miscellaneous
Property in Section

S

T

R

S

T

R

Register of Deeds Stamp & File Number

4. Lot No:

Recorded Plat:

5. Private Claims:

I, Craig W. McVean, in a field survey on July 16, 2015 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

5 - None

6 - None



B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

5 - CN 1/16 corner of Section 10, T26N, R14W - Nothing found.
Set stamped 2" aluminum cap on 5/8" x 34" rebar per standard BLM procedure.

6 - NE 1/16 corner of Section 10, T26N, R14W - Nothing found.
Set stamped 2" aluminum cap on 5/8" x 34" rebar per standard BLM procedure.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

5 - Stamped 2" aluminum cap on 5/8" x 34" rebar.
N02°E 28.35' to set N & T in W side 16" triple S. Maple
N74°E 12.64' to set N & T in S side 8" S. Maple
S07°W 13.88' to set N & T in E side 2" S. Maple
N88°W 24.50' to set N & T in SW side 5" twin S. Maple
Set Blue Composite Post with location tag 1' SW.

6 - Set stamped 2" aluminum cap on 5/8"x34" rebar.
S34°W 30.16' to set N & T in NW side 5" & 3" twin Cherry
S42°E 50.50' to set N & T in NE side 36" S. Maple
N05°E 33.27' to set N & T in W side 27" S. Maple
N51°W 11.27' to set N & T in NE side 8" Beech scribed 'XBT'
Set Blue Composite Post with location tag 1' SE.

Signed by:

Craig W. McVean

Date:

5/18/2016

Surveyor's Michigan License No.:

39088