LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in	
Benzie Located in: Corner Code #	
1. Public Land Survey T 27N R 13W E-13 T R	
2. Property Controlling S T R	
3. Miscellaneous S T R	
Property in Sec. S T R	Register of Deeds Stamp & File Numb
4. Lot No , Recorded Plat	
5. Private Claims	A B C D E F G H I J K L M 1
	3
I, <u>Craig W. McVean</u> , in a field survey on <u>July 20,19 98</u> do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:	4 - 7 · · · · · · · · · · · · · · · · · ·
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.	12 31 32 33 33 73 73 73 73 73 73 73 73 73 73 73
	05.44
A. Description of original monument and accessories and/or subsequent restoration:	SITE OF MICHIGAN
E-13 - GLO - Set post - Alvin Burt - 1839 Beech 8" N1°W 29L	CRAIG W.
Beech 9" N29°E 48L	PROFESSIONAL SURVEYOR
- GLO Exam. Survey - J. Hunt - 1850 FND.old post - Closing Corner is 32L. East	No. 38088
- Norton, Gourdie, Miller, Batzer – Notes - 1966 '+' Iron FND.	S ATOPESSIONAL SU
E. 22.34' & S. 0.3' to 1 ½" Pipe SW 73.23' Maple S. 49.53' Group Maple	2 2010
B. Description of corner evidence found and/or method applied in restoring or reestablishing	corner:
E-13 - Standard Corner common to Sec.'s 32&33, T27N,R13W - FND. ¾"x 1.15' long Rebar 0.2'x 0.2' by 1.8' long, down 1.3' and being 0.01' W & 0.05' S of top Iron. Accept the Monument in line w/ gravel Rd. N & 3'± N of E-W gravel Rd. CL. Fits GLO distance to accepted as the best available evidence of the position of the original corner.	oottom '+' Iron as corner monument.
C. Description of monument for corner and accessories established to perpetuate locating the	position of the corner:
E-13 - Replaced '+' Iron & Rebar w/ 3" Benzie Co. Brass Cap on %" Pipe encased w/ 4"x 36 cobble stones - down 0.5' N52°W 49.69' to set N&T in SW. Side U.P.	" Conc. Cylinder w/ small ring of
*N33°W 72.60' to set N&T in SW. Side 8" R. Pine *S32°W 55.93' to set N&T in SE. Side 6" R. Maple N34°E 40.22' to set N&T in W. Side R.R. Tie Anchor post East 22.36' (22.44' – GLO) to E-1, T26N,R13W	
*Nails by others above	
Signed by Cruix W. Mu Vern	Date 9/30/1998
Surveyor's Michigan License No. 39088	