## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

1 01 00111018 111			
Benzie (County)	Located In:	Corner Code #	
1. Public Land Survey	T R		
	TR		
0 B 1 0 1 11	TR		·
2. Property Controlling	S 32 T 27N R 14W	1	B. 14
in Section	S 29 T 27N R 14W	16	Register of Deeds Stamp & File Num
3. Miscellaneous	S TR		
Property in Sec.	S TR		
4. Lot No , Re	corded Plat		ABCDEFGHIJNIM
	<del></del> -		
<b>-</b>			2 5 5 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
5. Private Claims			4 7 - 8 9 10 11 12
			5
I, <u>Craig W. McVean</u> , in .	a field survey on April 30,	19 <u>97</u> do	6 18 17 16 15 14 13
hereby state that under requirement points mentioned in lines 1 and 2	above were in conformance with	f 1970, the corner	7
rules therefore as required in the i	CUMANT MARKIST OF SURVEY INSTRUCT	tions of the United	8 -19 -20 -21 -22 -23 -24
States Department of the Interior.	. Bureau of Land Management or	by a doggood of a	
Court of Law and for that the core	ner points mentioned in lines 3. 4	f and 6 above were	
in conformance with the rules of Decree of a Court of Law; established	the Michigan Board of Land Surv	eyors or by a	7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7
found as expressed below:	med, re-established, monumente	d, recovered,	
	rners. All in the same town o	nd range, may be recorded on this	12 31 32 33 34 35 36
certificate.	Protot an at the saile folding	nd lange, may be recorded on this	
A. Description of original mo	onument and accessories an	d/or subsequent restoration:	STATE OF MICHIGA
	<del>-</del>	-, -, - saccoquent reatoration.	ST ODALOW A
1 - None		10 11	CRAIG W.
<del></del>		<u>16</u> - None	BROSESSION I
			SURVEYOR ON NO.
			# % \
			18 33000 AUT
<ul> <li>B. Description of corner evidence</li> </ul>	dence found and/or method	applied in restoring or reestablishir	ng corner:
1 - W 1/16 Corner Sec. 29	& 32 -	16 - E 1/16 Corner Sec. 29	& 32 - Set 2" A.C.
Set 1" x 72" Galv. Iron	pipe w/2" A.C.	on 5/8" x 34" Rebar pe	r Standard BLM Procedure.
inside 2" x 24" Galv. ird BLM Procedure in Sprin	on Post per Standard		
DEM FROCEDURE IN SPIRI	J WILL MOIE.		
Description of monument f	or corner and accessories es	tablished to perpetuate locating th	Be position of the corner
			,
1 - Mon. per part B w/Blue	Carsonite Post	16 - Mon per part B w/Blue C	areanita Dant
N22°W 14.48' to N&T in NE Side Triple 14" Cedar N24°W 12 94' to N&T in Si			n SW Side R* C. Manta
N55°E 56.23' to N&T in	SE Side Twin 9" Cedar	N20°E 25.24' to N&T in	SF Side 8" S. Mania
N86°E 29.17' to N&T in S. Side 13" Cedar S88°E 49 59' to N&T in S. Side 6 S. Maple			S Side Twin 8" S. Mania
S38°W 29.61' to N&T in	SE Side 10" Cedar	S50°E 14.02' to N&T in	NE Side 17" R. Maple
igned by Craw II	V. Me Van		Des 9/29/1699
urveyor's Michigan License No	o. 39088		Date 9/29/1998
		<del>-</del>	· /