## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

| For corners in  | · <del>-</del>                        |
|---|---------------------------------------|
| BENZIE Located In: Corner Code #  |                                       |
| (County)  |                                       |
|   |                                       |
| 1. Public Land Survey T_27N R_14N F-9   |                                       |
| TR  |                                       |
| TR  |                                       |
| 2. Property Controlling S TR  |                                       |
| In Section S TR   |                                       |
| 3. Miscellaneous STR  |                                       |
| Property in Sec. S TR   | Register of Deeds Stamp & File Number |
| L   |                                       |
| 4. Lot No , Recorded Plat   |                                       |
| 5. Private Claims   | ABCDEFGHIJKL                          |
|   | 2 6 5 4 3 - 2 - 1 -                   |
|   | 3 1 1 1 1 1                           |
| 1 PADI T VIICVIIA — ha field summan TAMIADV 11 40 DL de handwatela Martin des   |                                       |
| I, <u>CARL T., KIISKILA</u> , in a field survey on <u>JANUARY 11</u> , 19 <u>96</u> do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in   | '  i   i   i   ī   ī   ī   ī          |
| conformance with regulations and rules therefore as required in the current manual of survey instructions of the  | 5                                     |
| United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or  | 6 18 17 16 15 14 13                   |
| that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan<br>Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented,         | 7                                     |
| recovered, found as expressed below:  | 8 19 20 21 22 23 24                   |
| NOTE: Not man than 2 comes of in the same burn and some may be seconded   |                                       |
| NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.   | 10 30 29 28 27 26 25                  |
| · ·   |                                       |
|   | 11 12 31 32 33 34 35 36               |
|   |                                       |
| A Description of principal manufact and accessories and/or subsequent restoration:  | 13                                    |
| Description of original monument and accessories and/or subsequent restoration:     F-9   |                                       |
| R. HAX HARRIS - JOB #83-2-331, JULY 11, 1991 - FOUND 3" ANGLE IRON, 8" MAPLE M50°N 2.0', 15" MAPLE S77°E 18.10', 10" MAPLE N60°E 40.70'.  | · .                                   |
| B. Description of corner evidence found and/or method applied in restoring or reestablishing corner F-9  FD ANGLE IRON FOR N1/4 CORNER S-28 AS USED BY P.S. MAX HARRIS FOR SUB'D. OF S-21, JOB \$83-FENCE REMAINS TO N & M. |                                       |
| $m{\cdot}$  |                                       |
|   |                                       |
|   |                                       |
|   |                                       |
|   |                                       |
| C. Description of monument for corner and accessories established to perpetuate locating the pos  | ition of the corner:                  |
| FD 3"x 2"x 24" ANGLE IRON, REPLACED W/BENZIE CO.  |                                       |
| REMON MON AND SET CARSONITE POST.   |                                       |
| 110" S.NAPLE N50"N 2.14'  |                                       |
| #13° S.MAPLE M55°E 40.70'   |                                       |
| # 5" S.MAPLE 577"E 17.97"   |                                       |
| #11" S.MAPLE \$10°E 13.03'  |                                       |
| #= PS, M.HARRIS 1991 WIT.   |                                       |
|   |                                       |
| 11001   |                                       |
| Surveyor's Michigan License No. 33781   |                                       |