

RECORDED

FEB 02 2000

SECTION

BRANCH COUNTY REMONUMATION PROGRAM  
LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN  
Branch County  
Recorded

11-08-1999 15:12:15

Linda Lee Morrison-Mathews  
REGISTER OF DEEDS

Liber 00004 Page 0016  
Register of Deeds Stamp & File Number

For corners in

BRANCH COUNTY BUTLER TWP	Located In:	Corner Code #
1. Public Land Survey	T 5 S R 5 W	L-7
	T R	
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S	
	T R	
3. Miscellaneous	S	
	T R	
Property in Sec.	S	
	T R	
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

ACCEPTED BY THE BRANCH COUNTY  
SURVEY PEER GROUP AS THE OFFICIAL  
CORNER UNDER MICHIGAN PUBLIC ACT 345  
OF 1990 AT A MEETING HELD ON  
OCT. 6, 1999  
E. R. Reed, Co. Rep.  
E. R. REED

I, EDWARD W. REED, in a field survey on SEPTEMBER 20, 19 99 do hereby  
state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned  
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in  
the current manual of survey instructions of the United States Department of the Interior,  
Bureau of Land Management or by a decree of a Court of Law and /or that the corner points  
mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board  
of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented,  
recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded  
on this certificate.

QUARTER CORNER COMMON TO SECTIONS 13 & 24

A. Description of original monument and accessories and/or subsequent  
restoration:  
1825: R. CLARK JR, DEPT. SURVEYOR , CORNER SET  
1889: J.H. BENNETT, SURVEYOR, FOUND THIN STONE WELL PLANTED, WITNESSED  
1916: C.B. NORTON, SURVEYOR, FOUND THIN LIMESTONE 1.6' BELOW SURFACE, WITNESSED  
1935: E.L. MINER, SURVEYOR, FOUND THIN POINTED LIME ROCK TWO WITNESS AGREEING

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:  
FOUND OLD GAS PIPE, NO TRACES OF STONE OR BRICK, FITTING 1 WITNESS OF BENNETT 1889 & NORTON 1916  
(HICKORY N 71 1/2 W 150 LINKS)

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:  
SET 1/2" X 18" REBAR IRON OVER GAS PIPE IN CI-MONUMENT BOX 4" BELOW GRAVEL ROAD SURFACE

NORTH	22.25	ROUND WOOD CORNER POST
SOUTH	22.06	R.R. TIE POST
N 71 1/2 W	99'	CENTER OF 36" HICKORY
N80W	147.4'	CENTER OF 24" HICKORY
NORTH	21.04'	TEL. PED

IN LINE WITH FENCE LINE NORTH

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													



AND IS ACCEPTED AS A CAREFUL AND FAITHFUL PERPETUATION  
OF THE POSITION OF THE ORIGINAL CORNER.

Signed by Edward W. Reed Date OCT. 6, 99  
EDWARD W, REED  
Surveyor's Michigan License No. 33985