

SURVEY & REMONUMENTATION

MAR 13 1998

SECTION

For corners in

BRANCH (County)
BATAVIA TOWNSHIP

Located In:

Corner Code ##

1. Public Land Survey T 6 S R 7 W K - 4
T R
T R
T R
2. Property Controlling S T R
in Section S T R
3. Miscellaneous S T R
Property in Sec. S T R
4. Lot No. , Recorded Plat
5. Private Claims

BRANCH COUNTY REMONUMENTATION CORNER
LAND CORNER RECORDATION CERTIFICATE
STATE OF MICHIGAN
Filing Requirement of Act 74, Mich. P.A. 1970
Branch County
Recorded

10-22-1997 09:53:29

Linda Lee Morrison-Mathews
REGISTER OF DEEDS

Liber 00003 Page 0138

Register of Deeds Stamp & File Number

I, EDWARD R. REED, in a field survey on JULY 03, 19 97, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- 1826: G.L.O. FIELDNOTES OF WM. BROOKFIELD, D.S. = "NORTH BETWEEN SECS. 11 & 12. 40.00 SET QR. SEC. POST. W. OAK 24 S68½E 71, W. OAK 7 S21½W 27."
1902: C. HAMILTON, CO. SURVEYOR = "FOUND STONE & BRICK AND MADE WITNESS."
1979: E. R. REED, CO. SURVEYOR, L.C.R.C. 1/240 = "FD. LARGE POINTED STONE, SURROUNDED BY BROKEN BRICKS. PLACED 1"x17" SOLID IRON OVER STONE."
1979: F. CUTCHER, RLS = "FD. 1" SOLID IRON IN C/L ROAD."

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND THE 1" SOLID IRON; REMOVED SAME.
RESET A 1/2" x 18" STEEL REBAR ROD, WITH BRANCH COUNTY REMONUMENTATION CAP, IN CONCRETE, AND IN C-I MONUMENT BOX; IN C/L EAST-WEST ROAD PAVEMENT.

AND IS ACCEPTED AS A CAREFUL AND FAITHFUL PERPETUATION OF THE POSITION OF THE ORIGINAL CORNER.


C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- 1/2" x 18" STEEL REBAR ROD, WITH BRANCH COUNTY REMONUMENTATION CAP, IN CONCRETE, OVER STONE & BRICKS, AND IN C-I MONUMENT BOX;
IN C/L EAST-WEST ROAD PAVEMENT.
N 05 W 52.8' - CENTER TWIN 14" OAK.
S 80 W 77.0' - CENTER 36" MAPLE STUMP.
S 82 W 86.7' - FACE OF TEL. POLE.
N 40 W 45.1' - CENTER OF 12" DOUBLE MAPLE.

ACCEPTED BY THE BRANCH COUNTY SURVEY PEER GROUP AS THE OFFICIAL CORNER UNDER MICHIGAN PUBLIC ACT 345 OF 1990 AT A MEETING HELD ON 9-10-97

E.R. Reed, Co. Rep.
E. R. REED, P.S.

Signed by EDWARD R. REED, P.S.
Surveyor's Michigan License No. 7437



JULY 03, 1997