SURVEY & REMONUMENTATION

MAR 1 3 1998

SECTION

BRANCH COUNTY REMONUMENTATION CORNER

LAND CORNER RECORDATION CERTIFICATE

Ear	corners in		riling Rei	quirement of Act /	4, MICR. P.A. 19	70					
BRANCH (County)		Located In:		Corner Cod	le <i>#</i> #	STATE OF MICHIGAN Branch County					
8ETHEL TOWNS		HIP	T 7 S R 7 W T R T R			Recorded 10-22-1997					
	Property Controlling In Section	S	T R T R T R			Linda Lee REGISTER O Liber ÜÜ	F DEEDS	3	- · · ·		
	Miscellaneous Property in Sec.		T R T R		F	Register of Dee		p & File	∍ Nun	nber	
4.	Lot No,	Recorded	! Plat			BETHEL TOW		: а ы	1 1	¥ ∣	f
	Private Claims					2 6 3	5 4	3-	- 2	, ,	<u> </u>
				lui v oz	0.7	4 - 7 -	8 9			1	-12
I, _E do h	DWARD R. REED, ereby certify that under re	P, Sn a fie equirement	eld survey on	JUL 1 U3 P.A. of 1970, the comer	, 19 <u>9 /</u> , points mentioned	5		+	+	_	+
in lia	nes 1 and 2 above were ent manual of survey inst	in conform	ance with regulation	is and rules therefore a	is required in the	6 - 18	17—16	15-			13-
Man abov Cou	agement or by a decree o we were in conformance w it of Law; established, essed below:	f a Court of ith the rule	Law and/or that the c es of the Michigan Bo	corner points mentioned ard of Land Surveyors o	in lines 3, 4 and 5 r by a Decree of a	9	20 -21	22	2:		24
•	E: Not more than 4 on this certificate	_	all in the same tow	n and range, may be	recorded	11 12 31 13	32 - 33	34-	35	;	36-
A.	Description of original	monume	nt and accessories	and/or subsequent	restoration;	13	-l .				+-
	1875: HAMILTON	O BEEC - (REF	H 18 N60W 11" Erenced surve	•)
	1875: HAMILTON,				IEL. FD. STAK	KE & STONE	I LINK	NORT	H &		
	1976: E. R. REE AND OL	D, CO. D SURV	SURVEYOR - L EY NOTE REMA!	.C.R.C. 1/190 = NING WITNESS.	RESET CORNE	ER IN ROAD I	FROM O	VID C	ORNE	R	
В.	1976: E. R. REE Description of corner of				ng or reestablishii	ng corner:					
	FOUND CORNER M				10. 1/190, BE	EING A 1/2"	IRON I	ROD, I	WITH	RLS	5

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: BRANCH COUNTY REMONUMENTATION CAP ON 1/2" IRON ROD, IN MONUMENT BOX, IN ROAD PAYEMENT:

AND IS ACCEPTED AS A CAREFUL AND FAITHFUL PERPETUATION OF THE POSITION

REMOVED RLS CAP FROM ROD AND, PLACED A BRANCH COUNTY REMONUMENTATION CAP ON ROD.

N 30 E 73.6' - S.E. CORNER OF HOUSE.

S 45 W 50.3' - P. POLE.

OF THE ORIGINAL CORNER.

SOUTH 8.3' - C/L EAST WEST ROAD PAVEMENT.

NORTH 66.20' - SOUTH FACE OF CONCRETE PORCH (ON N-S TOWNSHIP LINE).

PLACED CONCRETE IN BOTTOM OF MONUMENT BOX AROUND IRON ROD.

SOUTH 65.34' - SECTION CORNER TO OVID TOWNSHIP.

ACCEPTED BY THE BRANCH COUNTY SURVEY PEER GROUP AS THE OFFICIAL CORNER UNDER MICHIGAN PUBLIC ACT 345 OF 1990 AT A MEETING HELD ON

Co. Rep.

Signed by

JULY 03, 1997



7437 Surveyor's Michigan License No. FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971