## SURVEY & REMONUMENTATION

MAR 1 3 1998

SECTION

## **BRANCH COUNTY REMONUMENTATION CORNER**

LAND CORNER RECORDATION CERTIFICATE OF MICHIGAN

	Filing Requirem	ent of Act 74, Mich. P.A	1. 1970 Franch County
For corners in	-		Recorded
BRANCH (County)	Located In:	Corner Code #	10-22-1997 09:55:32
GILEAD TWP.			Linda Lee Morrison-Mathews
1. Public Land Survey		-7	REGISTER OF DEEDS
·	TR TR		Liber 00003 Page 0155
2. Property Controlling S in Section S	_ TR _ TR		
· · · · · · · · · · · · · · · · · · ·	TR		Register of Deeds Stamp & File Number
Property in Sec. S	TR		
4. Lot No, Recorded P	lat		A B C D'E F G H I J K L M
5. Private Claims			1
			2 6 5 3 2 1
			3 1 1 1 1 1 1 2
I, EDWARD W. REED	. in a field survey on	APRIL 29_, 19 97_ do hereb	
state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual			
and 2 above were in conformance with re of survey instructions of the United State	guiations and rules therefore as Department of the Interior,	as required in the current manu , Bureau of Land Management (	
by a decree of a Court of Law and /or that	t the carner points mentioned	l in lines 3, 4 and 5 above were i	in 0 10 20 21 22 23 24
conformance with the rules of the Michiga established, re-established, monumented,	in Board of Land Surveyors o , recovered, found as express	or by a Decree of a Court of Lav sed below:	9
			10 30 29 28 27 26 25
NOTE: Not more than 2 corners, all in the same town and range, may be recorded			11
on this certificate.			12 31 32 33 34 35 36
•			ACCEPTED BY THE BRANCH COUNTY
A. Description of original monument and accessories and/or subsequent restoration:			ACCEPTED BY THE BRANCH COUNTY SURVEY PEER GROUP AS THE OFFICIAL CORNER UNDER MICHIGAN PUBLIC ACT 345
QUARTER CORNER COMMON	TO SECTIONS 13 & 2	24	OF 1990 AT A MEETING HELD ON
1828: R. CLARK jr, DEPT. SURV	VEYOR - SET CORNE	R	EIR. Read, P.S.Co. Rep.
OLD NOTES: INDICATE IRON I			E.R.REED
1965: PLAT OF "OAK HAVEN N			
	The state of the s	AFT WITH COLLAR SU	RROUNDED BY BROKEN STONES
RECORDED IN LCRC # 0	070		
B. Description of corner evidence	found and/or method app	lied in restoring or reestablis	shing corner:
FOUND IRON SHAFT WITH CO	LLAR SURROUNDED	BY BROKEN STONES	WITH FLAGGING
SET 1/2" X 18" REBAR IRON WI	TH REMON CAP IN C	I-MONUMENT BOX	
			•
C. Description of monument for corr	ner and accessories estab	olished to perpetuate locatin	g the position of the corner:
IN C/L OF EAST-WEST GRAVE	L ROAD		
IN LINE WITH FENCES RUNNI		ЛH	
RR-RAIL ANCHOR POST, SOU			
TEL. PED N69W 85.7' TO FACE			
18" WALNUT, N53W 45.9' TO C	ENTER		
AND IS ACCEPTED AS A CARE	EFUL AND FAITHFUL	PERPETUATION OF TH	IE POSITION OF THE ORIGINAL CORNER
	/1 .		
Signed by	. Nuf	and the same of th	Date APRIL 29, 1997
EDWARD W. RI	EED' /	ST MICH	
		EDWARD Y	
Surveyor's Michigan License No	. 33800 1	W. REED	
-	2	LAND SURVEYOR	•
	7	L	P

REVISED MAY 14,1975