## SURVEY & REMONUMENTATION

## APPROVED

Date 2 - マ - 94 川 CALHOUN COUNTY REMONUMENTATION.

For corners in

4. Lot No.

5. Private Claims \_

This document is being re-recorded to correct Town designation.

APR 2 6 1995

CALHOUN COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

COMMISSION

	Calhoun	_ Located In:	Corner Code ##
	newton Jup. Public Land Survey		
1.	Public Land Survey	T R	
		T R	4 1 1
		T R	other was
		T B	# 1
2.	Property Controlling	S T R	41
	in Section	S T R	421
3.	Miscellaneous	s <u>27</u> т <u>3 S.</u> в <u>7 W</u> .	240
	Property in Sec.	S T R	

\_ , Recorded Plat \_

STATE OF MICHIGAN CALHOLIN COUNTY RECORDED

13 DEC 94 3:49 P.H.

ANNE B. NORLANDER Register of Deed's Stabilp Chille Number

I. Michael A. Groat, in a field survey on January do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

10 11 12

A. Description of original monument and accessories and/or subsequent restoration:

Original Survey:

Sibley 1826

Set meander post on North and South side of Lee Lake

Post on South side:

3 chains North of SW corner

set post, from which:

7" White oak, East, 85 links

26" White oak, S27"W, 78 links

Post on North side:

56.65 chains North of SW corner

set post from which

6" Black Oak, S69 W 4 links 6" Black Oak, N7 W 9 links

anything set or found in re-surve

No record of

Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found no evidence of meander corners. Traversed between G-9 and G-11 and set new meander corners.

CLERK - REGISTER OF DEEDS ANNE B. NORLANDER

SO DEC 64 1:24 b'W'

KECOKDED CALHOUN COUNTY SIVIE OF MICHIGAN # 1 LIBER 1780 PAGE 627

**せ** LIBER 1781 PAGE 675

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner." Set Berntsen monuments 231' North of G-11 and 1629.4' South of G-9 on Section line.

Witnesses: South shore

Nail and spotter in 6" Cherry, N50°E, 1.7' Nail and spotter in 14" Oak, S70°W, 32.7' Nail and spotter in 6"COak, S10°E, 16.6' 231' North of Southwest corner of Sec. 27

North shore Nail and spott Nail and spott Nail and spot Nail and spot

\_ Date

North, 61.8 86 E, 61.2' W, 99.5 91.4 No. 39079 POFESSION

Surveyor's Michigan License No.

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971