

Date 11/17/99 RRL
CALHOUN COUNTY
REMONUMENTATION.
For corners in

STATE OF MICHIGAN
CALHOUN COUNTY
RECORDED

CALHOUN
(County)
CLARENDON TWP.

ANNE B. NORLANDER
CLERK-- REGISTER OF DEEDS

LIBER 2186 PAGE 6

Register of Deeds Stamp & File Number

1. Public Land Survey		T4S	R5 W	L-9
		T	R	
		T	R	
		T	R	
2. Property Controlling in Section	S	T	R	
	S	T	R	
3. Miscellaneous Property in Sec.	S	T	R	
	S	T	R	

4. Lot No. _____, Recorded Plat _____

5. Private Claims

I, Frederick J. Cutcher, in a field survey on August 24, 1999 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

GLO, Robert Clark, Jr., 1825: 10" Burr Oak S. 76° W. 59 lks.; 12" Burr Oak S. 76° E. 57 lks.

Wit ness Card from Crane, 1964 (no name): 1 ½" Round Steel Bar; 20" Hickory N. 21° W. 81.8'; 20" Hickory N. 77° W. 108.1'; 12" Elm S. 60° W. 70.0'; 20" Maple S. 62° E. 45.5'.

Witness Card from Carr (no name or date): 16" Hickory N. 22° 30' W. 87.4'; 16" Maple N. 51 E. 35.8'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1 1/2" diameter iron with 1/2" x 18" iron on East side surrounded with rocks at bottom. Two references remain.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Replaced 1 ½" diameter iron and ½" x 18" iron with Berntsen Monument in Monument Box and is accepted as the best available evidence of the position of the original corner.

In centerline of T Drive S.; in line with fence to South; face of round steel corner post N. 44° E. 43.40'; Nail and Spotter 42" Maple S. 58° E. 44.87'; Nail and Spotter 12" Maple S. 1° W. 32.36'; Nail and Spotter 30" Hickory N. 18° W. 81.47'.

Signed by Fredrick J. Cuthbert
Surveyor's Michigan License No. 24592

Date 11/15/99

SURVEY & RECOMMENDATION

MAR 13 2000

SECTION